



THE DRIVELINE EXPERTS



Buyers Guide for U-joint Application



Neapco Genuine

Neapco OE Series

Neapco Performance Series

Manufacturing Driveline Solutions®
in the USA Since 1921.

NeapcoAftermarket.com

Part#	Application
1-0005*	Jaguar 2.4 57-56; Jaguar 3.4 60-57; Jaguar 3.8 61-60; Jaguar C-Type 53; Jaguar D-Type 56-54; Jaguar Mark IX 61-59; Jaguar Mark VII 57-53; Jaguar Mark VIII 58-57; Jaguar XK120 54-53; Jaguar XK140 57-55; Jaguar XK150 61-58; Jaguar XKE 61; Jaguar XKSS 57; Land Rover Land Rover 62-50; Land Rover Range Rover 98-87; Rover 2000 73-68; Rover 3500 74-72; Rover 3500 80; Rover 3500S 74-69; Triumph Stag 73-71; Triumph TR2 56-53; Triumph TR3 57-55; Triumph TR3A 62-57; Triumph TR3B 62; Triumph TR4 65-61; Triumph TR4A 68-65; Triumph TR6 76-69; Volvo 240 93-90; Volvo 242 84-75; Volvo 244 89-75; Volvo 245 89-75; Volvo 262 76; Volvo 262 81-78; Volvo 264 82-76; Volvo 265 81-76; Volvo 740 92-85; Volvo 760 90-83; Volvo 940 95-91; Volvo 960 94-92
1-0011*	Toyota Corolla 79-68
1-0013*	Toyota Carina 73-71; Toyota Celica 81-71; Toyota Corolla 84-71; Toyota Corona 82-67; Toyota Cressida 87-78; Toyota Mark II 76-72; Toyota Van 85-84
1-0027*	Nissan 240Z 73-71; Nissan 260Z 75-74; Nissan 280Z 78-75; Nissan 510 73-68; Nissan 510 79-78; Nissan 521 Pickup 72-69; Nissan 610 76-73; Nissan 620 79-72; Nissan 710 77-74; Nissan 720 85-80; Nissan D2189-87; Nissan Pathfinder 88; Subaru Brat 87-78; Subaru DL 80-75; Subaru GL 80-79
1-0028	Nissan 1200 73-71; Nissan B110 73-71; Toyota Starlet 84-81
1-0029	INFINITI QX4 03-97; Nissan 200SX 83-78; Nissan 240Z 73-71; Nissan 260Z 75-74; Nissan 280Z 78-75; Nissan 280ZX 83-79; Nissan 510 73-68; Nissan 610 76-73; Nissan 720 86-82; Nissan 810 81-77; Nissan D2194-86; Nissan Maxima 84; Nissan Pathfinder 04-87; Nissan Pickup 97-95
1-0105*	American Motors American 65-64; Ford Econoline 67-61; Ford Falcon 68-60; Ford Mustang 69-64; Mercury Caliente 65-64; Mercury Comet 65-60; Mercury Cyclone 65-64
1-0134	Ford F-100 69-59; Ford F-100 74-73; Ford F-100 78-76; Ford F-150 78-75; Ford F-250 78-59; Ford F-350 74-67; Ford P-100 68; Ford P-100 70; Lincoln Continental 62-61; Mercury Colony Park 60; Mercury Montclair 60; Mercury Monterey 60
1-0153 1-0153G 1-0153P	American Motors Ambassador 74-67; American Motors American 68; American Motors AMX 74-68; American Motors AMX 80-78; American Motors Concord 83-78; American Motors Eagle 88-80; American Motors Gremlin 78-70; American Motors Hornet 74-70; American Motors Javelin 74-68; American Motors Matador 78-71; American Motors Pacer 80-75; American Motors Rambler 69; American Motors Rebel 70-67; American Motors Spirit 83-79; Avanti II 84-75; Buick Apollo 75-73; Buick Skyhawk 80-75; Buick Skylark 79-75; Checker Marathon 68-62; Checker Marathon 81-72; Chevrolet Bel Air 75; Chevrolet Bel Air 75; Chevrolet Biscayne 70-58; Chevrolet Blazer 74-69; Chevrolet Blazer 91-87; Chevrolet Brookwood 61-58; Chevrolet Brookwood 70-69; Chevrolet C10 81-75; Chevrolet C10 Panel 67-60; Chevrolet C10 Pickup 74-61; Chevrolet C10 Suburban 81-60; Chevrolet C20 81-75; Chevrolet C20 Panel 67; Chevrolet C20 Pickup 74-62; Chevrolet C20 Suburban 81-68; Chevrolet C30 78-75; Chevrolet C30 Panel 66-60; Chevrolet C30 Pickup 74-61; Chevrolet Camaro 75-67; Chevrolet Camaro 93-88; Chevrolet Caprice 68-66; Chevrolet Caprice 75; Chevrolet Chevelle 72-64; Chevrolet Chevy II 68-62; Chevrolet Colorado 12-04; Chevrolet Corvair 69-60; Chevrolet Corvette 70-53; Chevrolet Corvette 81-80; Chevrolet Corvette 97-84; Chevrolet El Camino 87-65; Chevrolet G10 84-75; Chevrolet G10 Van 74-64; Chevrolet G20 81-75; Chevrolet G20 Van 74-67; Chevrolet G30 77-75; Chevrolet G30 Van 74-71; Chevrolet Impala 70-59; Chevrolet Impala 75; Chevrolet K10 86-75; Chevrolet K10 Pickup 74-60; Chevrolet K10 Suburban 86-60; Chevrolet K20 86-75; Chevrolet K20 Pickup 74-61; Chevrolet K20 Suburban 86-61; Chevrolet K30 86-77; Chevrolet K5 Blazer 86-75; Chevrolet Malibu 67-64; Chevrolet Monte Carlo 72-70; Chevrolet Monza 80-75; Chevrolet Nova 79-69; Chevrolet P10 80-75; Chevrolet P10 Series 67-60; Chevrolet P10 Van 74-68; Chevrolet P20 81-75; Chevrolet P20 Series 67; Chevrolet P20 Van 74-68; Chevrolet P30 90-75; Chevrolet P30 Series 67-60; Chevrolet S10 94-88; Chevrolet S10 Blazer 94-88; Chevrolet Suburban 66-60; Chevrolet V10 87; Chevrolet V10 Suburban 88-87; Chevrolet V1500 Suburban 91-89; Chevrolet V20 87; Chevrolet V20 Suburban 88-87; Chevrolet V2500 Suburban 91-89; Chevrolet V30 88-87; Chevrolet V3500 91-89; Chevrolet Vega 77-71; Dodge Dakota 10-87; Dodge Durango 08-98; Dodge Ram 2500 94; Dodge Ramcharger 77-75; Dodge W100 77-75; Dodge W150 77; Dodge W200 77-75; Dodge W300 77-75; Edsel Bermuda 58; Edsel Citation 58; Edsel Corsair 59-58; Edsel Pacer 58; Edsel Ranger 60-58; Edsel Roundup 58; Edsel Villager 60-58; Ford Aerostar 97-86; Ford Bronco 78-75; Ford Bronco 91; Ford Bronco II 90-84; Ford Consul 60-56; Ford Country Sedan 60-50; Ford Country Sedan 74-66; Ford Country Squire 60-50; Ford Country Squire 74-66; Ford Country Squire 91-87; Ford Crown Victoria 94-92; Ford Custom 300 60-57; Ford Custom 500 72-70; Ford Custom 500 77-75; Ford Custom 52-50; Ford Custom 57; Ford Custom 72-66; Ford Customline 56; Ford Del Rio Wagon 58-57; Ford E-100 Econoline 78-68; Ford E-100 Econoline Club Wagon 78-75; Ford E-150 Econoline 78-75; Ford E-150 Econoline Club Wagon 78-75; Ford E-200 Econoline 74-68; Ford E-300 Econoline 74-68; Ford Econoline 67-61; Ford Elite 76-75; Ford Escape 12-01; Ford Explorer 11-91; Ford Explorer 22-20; Ford Explorer Sport 03-02; Ford Explorer Sport Trac 05-01; Ford Explorer Sport Trac 10-07; Ford F152-48; Ford F-100 83-53; Ford F-150 03-00; Ford F-150 78-75; Ford F-150 Heritage 04; Ford F2 52-48; Ford F2 52-48; Ford F3 52-48; Ford F3 52-48; Ford F-350 76-53; Ford F4 52-48; GMC Fairlane 60-55; Ford Fairlane 70-66; Ford Fairmont 83-78; Ford Falcon 70-69; Ford Falcon Sedan Delivery 63-61; Ford Galaxie 500 66-63; Ford Galaxie 500 72-69; Ford Galaxie 60-59; Ford Galaxie 67-66; Ford Gran Torino 76-72; Ford Granada 82-75; Ford LTD 86-75; Ford LTD Crown Victoria 91-87; Ford Mainline 56; Ford Maverick 77-70; Ford Mustang 21-19; Ford Mustang 67-64; Ford Mustang 73-70; Ford Mustang 95-79; Ford P-100 73-60; Ford P-350 74-60; Ford Pinto 80-75; Ford Ranch Wagon 60-56; Ford Ranchero 60-57; Ford Ranchero 77-75; Ford Ranger 11-83; Ford Ranger 21-19; Ford Thunderbird 93-80; Ford Torino 76-68; GMC 1500 Series 65-61; GMC 2500 Series 65-61; GMC C15 78-75; GMC C15 Suburban 78-75; GMC C15/C1500 Pickup 74-66; GMC C15/C1500 Suburban 74-68; GMC C1500 81-79; GMC C1500 Suburban 81-79; GMC C25 78-75; GMC C25 Suburban 78-75; GMC C25/C2500 Pickup 74-66; GMC C25/C2500 Suburban 74-68; GMC C2500 81-79; GMC C2500 Suburban 81-79; GMC C35 78-75; GMC C35 Pickup 66; GMC C35/C3500 Pickup 74-67; GMC C3500 81-79; GMC Caballero 87-78; GMC Canyon 12-04; GMC G15 78-75; GMC G15/G1500 Van 74-67; GMC G1500 81-79; GMC G25 78-75; GMC G25/G2500 Van 74-67; GMC G2500 81-79; GMC G35 77-75; GMC G35/G3500 Van 67; GMC G35/G3500 Van 74-70; GMC Jimmy 94-70; GMC K15 78-75; GMC K15 Suburban 78-75; GMC K15/K1500 Pickup 74-67; GMC K15/K1500 Suburban 74-67; GMC K1500 86-79; GMC K1500 Suburban 86-79; GMC K25 78-75; GMC K25 Pickup 66; GMC K25 Suburban 78-75; GMC K25/K2500 Pickup 74-67; GMC K25/K2500 Suburban 74-68; GMC K2500 86-79; GMC K2500 Suburban 86-79; GMC K35 78-77; GMC K3500 86-79; GMC P15 78-75; GMC P15/P1500 Van 74-67; GMC P1500 80-79; GMC P25 78-75; GMC P25/P2500 Van 74-67; GMC P2500 81-79; GMC P35 78-75; GMC P3500 90-79; GMC PB 15 Series 66; GMC PB1500 Series 65-63; GMC S15 90-88; GMC S15 Jimmy 91-88; GMC Sonoma 94-91; GMC Sprint 77-71; GMC Cyclone 91; GMC Typhoon 93-92; GMC V1500 87; GMC V1500 Suburban 91-87; GMC V2500 87; GMC V2500 Suburban 91-87; GMC V3500 91-87; Honda Passport 02-94; Hyundai Santa Fe 06-01; INFINITI QX56 13-04; International AM120 65-57; International AM300 65-57;

* Lube Fitting in Bearing Cap

Part#	Application
1-0153 1-0153G 1-0153P (Cont.)	International M700 67-65; International M800 71-65; International Scout II 80-75; Isuzu Amigo 00-98; Isuzu Axiom 04-02; Isuzu i-350 06; Isuzu i-370 08-07; Isuzu Pickup 95-90; Isuzu Rodeo 04-91; Isuzu Rodeo Sport 03-01; Jaguar 3.8 66-62; Jaguar 340 67; Jaguar 420 67; Jaguar Mark X 66-62; Jaguar Vanden Plas 87-82; Jaguar XJ 71-69; Jaguar XJ 12 79-73; Jaguar XJ 12 87-81; Jaguar XJ6 87-72; Jaguar XJS 87-76; Jaguar XKE 74-62; Jeep Cherokee 01-74; Jeep CJ3 59; Jeep CJ5 83-59; Jeep CJ5A 68-66; Jeep CJ6 75-59; Jeep CJ6A 68-66; Jeep CJ7 86-76; Jeep Comanche 92-86; Jeep Commando 73-66; Jeep Gladiator 69-63; Jeep Grand Cherokee 04-93; Jeep Grand Wagoneer 91-84; Jeep Grand Wagoneer 93; Jeep J 10 88-74; Jeep J20 88-74; Jeep Jeepster 71-67; Jeep Liberty 06-02; Jeep Liberty 07; Jeep Scrambler 85-81; Jeep TJ 06-97; Jeep Wagoneer 67-63; Jeep Wagoneer 90-70; Jeep Wrangler 06-97; Jeep Wrangler 22-12; Jeep Wrangler 95-87; Jeep Wrangler JK 18; Land Rover Land Rover 74-50; Land Rover Range Rover 74-70; Lincoln Aviator 05-03; Lincoln Aviator 22-20; Lincoln Capri 59-52; Lincoln Continental 62-58; Lincoln Continental 80; Lincoln Continental 87-82; Lincoln Cosmopolitan 54-49; Lincoln Custom 55; Lincoln Lincoln 51-50; Lincoln Mark II 57-56; Lincoln Mark VI 83-80; Lincoln Mark VII 92-84; Lincoln Premier 60-56; Lincoln Town Car 94-81; Lincoln Versailles 80-79; Mazda B2300 97-94; Mazda B3000 02-94; Mazda B3000 05; Mazda B4000 10-94; Mazda Navajo 94-91; Mazda Tribute 06-01; Mazda Tribute 11-08; Mercedes-Benz ML320 03-98; Mercedes-Benz ML350 05-03; Mercedes-Benz ML430 01-99; Mercedes-Benz ML500 05-02; Mercedes-Benz ML55 AMG 03-00; Mercury Colony Park 60-57; Mercury Colony Park 91-90; Mercury Comet 69-63; Mercury Cougar 73-67; Mercury Cougar 93-80; Mercury Custom 56-55; Mercury Grand Marquis 94-77; Mercury Mariner 11-05; Mercury Marquis 86-77; Mercury Medalist 58-56; Mercury Monarch 80-75; Mercury Montclair 60-55; Mercury Montego 76-68; Mercury Monterey 60-55; Mercury Mountaineer 10-97; Mercury Turnpike Cruiser 57; Mercury Zephyr 83-78; MG/MGC 69-68; Mitsubishi Raider 09-06; Nissan Armada 15-05; Nissan D2194-86; Nissan Frontier 19-98; Nissan Pathfinder 02-87; Nissan Pathfinder 12-05; Nissan Pathfinder Armada 04; Nissan Pickup 97-95; Nissan Titan 15-04; Nissan Titan 18; Nissan Titan XD 21-16; Nissan Xterra 15-00; Oldsmobile 88 57; Oldsmobile 98 64-57; Oldsmobile Bravada 94-91; Oldsmobile Omega 79-73; Oldsmobile Starfire 63-61; Oldsmobile Starfire 80-75; Oldsmobile Super 88 64-57; Plymouth Trailduster 76-75; Pontiac Astre 77-75; Pontiac Firebird 75-67; Pontiac Firebird 93-88; Pontiac Grand Safari 74-71; Pontiac Parisienne 86; Pontiac Phoenix 79-77; Pontiac Sunbird 80-76; Pontiac Ventura 77-71; Ram Dakota 11; Rover 2000 73-68; Rover 3500 74-72; Rover 3500 80; Rover 3500S 74-69; Suzuki Equator 12-09; Toyota Pickup 95-89; Toyota Previa 97-95; Toyota Sequoia 04-01; Toyota T 100 98-93; Toyota Tacoma 08-95; Toyota Tacoma 20-18; Toyota Tundra 06-00; Volvo 164 75; Volvo 242 84-75; Volvo 244 84-75; Volvo 245 84-75; Volvo 262 76; Volvo 262 81-78; Volvo 264 82-76; Volvo 265 81-76; Volvo 740 92-85; Volvo 745 85; Volvo 760 90-83; Volvo 780 91-87; Volvo DL 84
1-0154*	Isuzu Rodeo 04-03; Isuzu Rodeo Sport 03; Jeep CJ3 66-60
1-0170	Dodge W100 Pickup 59-58; Dodge W100 Pickup 74-68; Dodge W100 Series 67-60; Dodge W200 Series 67-61; Dodge W300 Pickup 71-68; Dodge W300 Series 67-60
1-0171*	Chevrolet Avalanche 1500 06-02; Chevrolet C10 81-79; Chevrolet C1500 89-88; Chevrolet C1500 98-91; Chevrolet C1500 Suburban 93-92; Chevrolet C1500 Suburban 99-96; Chevrolet Chevelle 72-71; Chevrolet Colorado 12-04; Chevrolet G10 95-92; Chevrolet G20 78-76; Chevrolet G20 95-92; Chevrolet K1500 89-88; Chevrolet K1500 93-91; Chevrolet K1500 99-97; Chevrolet K1500 Suburban 96-95; Chevrolet K2500 89-88; Chevrolet K2500 91; Chevrolet K3500 89-88; Chevrolet P30 79; Chevrolet S10 96-94; Chevrolet Silverado 1500 06-99; Chevrolet Silverado 1500 Classic 07; Chevrolet Suburban 1500 06-00; Chevrolet V30 88; Chevrolet V3500 89; Ford Bronco 87; Ford Bronco 89; Ford F-350 89-87; Ford F-350 93-91; GMC C1500 81-79; GMC C1500 89-88; GMC C1500 91; GMC C1500 98-93; GMC C1500 Suburban 81-79; GMC C1500 Suburban 93-92; GMC C1500 Suburban 99-95; GMC Canyon 12-04; GMC G1500 95-92; GMC G25 78-75; GMC G2500 95-91; GMC K1500 93-88; GMC K1500 99-95; GMC K1500 Suburban 96-95; GMC K2500 91-88; GMC K3500 89-88; GMC P2500 79; GMC P35 78; GMC Sierra 1500 06-99; GMC Sierra 1500 Classic 07; GMC Sierra 1500 HD 01; GMC Sonoma 96-94; GMC V2500 87; GMC V2500 Suburban 88-87; GMC Yukon XL 1500 06-04; Isuzu i-280 06; Isuzu i-290 08-07; Isuzu i-350 06; Isuzu i-370 08-07; Jeep TJ 06-03; Jeep Wrangler 06-03; Pontiac Firebird 68-67
1-0174	Chevrolet Blazer 71-69; Chevrolet K10 Pickup 71-60; Chevrolet K10 Suburban 71-60; Chevrolet K20 Pickup 71-61; Chevrolet K20 Suburban 71-61; Chevrolet Suburban 66-60; Dodge W100 Pickup 59-58; Dodge W100 Pickup 71-68; Dodge W100 Series 67-60; Dodge W200 Pickup 71-68; Dodge W200 Series 67-61; Ford Bronco 77-66; Ford F-100 71-59; Ford F-250 70-59; Ford F-250 72; GMC 1500 Series 65-61; GMC 2500 Series 65-61; GMC Jimmy 71-70; GMC K15/K1500 Pickup 74-67; GMC K15/K1500 Suburban 71-67; GMC K25 Pickup 66; GMC K25/K2500 Pickup 71-67; GMC K25/K2500 Suburban 71-68; International 1000C 69-68; International 1000D 70-69; International 1100C 69-68; International 1100D 70-69; International 1200C 69-68; International 1200D 70-69; International Scout 71-61; International Scout II 73-71; Jeep Cherokee 98-84; Jeep CJ3 66-59; Jeep CJ5 83-59; Jeep CJ5A 68-66; Jeep CJ6 75-59; Jeep CJ6A 68-66; Jeep CJ7 86-76; Jeep Comanche 92-86; Jeep Commando 73-66; Jeep Gladiator 69-63; Jeep Grand Cherokee 98-93; Jeep Grand Wagoneer 93; Jeep Jeepster 71-67; Jeep Scrambler 85-81; Jeep Wagoneer 73-66; Jeep Wagoneer 90-84; Jeep Wrangler 95-87
1-0175*	Chevrolet Blazer 71-69; Chevrolet K10 Pickup 72-64; Chevrolet K10 Suburban 72-68; Chevrolet K20 Pickup 72-60; Chevrolet K20 Suburban 72-68; Dodge W100 Pickup 72-68; Dodge W100 Series 67-61; Dodge W200 Pickup 72-68; Dodge W200 Series 67-61; Ford Bronco 77-66; Ford F-100 68-65; Ford F-250 74-60; GMC Jimmy 72-70; GMC K15 76-75; GMC K15/K1500 Pickup 74-66; GMC K15/K1500 Suburban 72-67; GMC K25/K2500 Pickup 72-67; International 1000A 66; International 1000B 67; International 1000C 68; International 1000D 70-69; International 1200A 66; International 1200B 67; International 1200C 68; International 1200D 70-69; International 1210 73-71; International 900A 67-66; International Scout 71-61; International Scout II 73-71; Jeep Cherokee 94-84; Jeep CJ5 83-63; Jeep CJ6 75-63; Jeep CJ7 86-76; Jeep Comanche 92-86; Jeep Commando 73-67; Jeep Gladiator 69-63; Jeep Grand Cherokee 93; Jeep J-2600 73-65; Jeep J-2700 70-65; Jeep J-2800 68-65; Jeep J-3500 70-65; Jeep J-3600 70-65; Jeep J-3700 70-65; Jeep J-3800 71-65; Jeep Jeepster 71-67; Jeep Scrambler 85-81; Jeep Wagoneer 74-63; Jeep Wagoneer 90-84; Jeep Wrangler 95-87
1-0221	Alfa Romeo 1900 58-54; Alfa Romeo 1900C 57-54; Alfa Romeo 2000 62-58; Alfa Romeo 2600 68-62; Alfa Romeo Berlina 74-69; Alfa Romeo Duetto 1600 68-66; Alfa Romeo Giulia 68-62; Alfa Romeo Giulia Sprint 68-62; Alfa Romeo Giulietta 63-54; Alfa Romeo GT Veloce 74-69; Alfa Romeo GTA 68-65; Alfa Romeo GTC 66-64; Alfa Romeo GTV 65; Alfa Romeo GTV 68-67; Alfa Romeo GTZ 64; Alfa Romeo Montreal 75-71; Alfa Romeo Spider 78-69; Alfa Romeo Sport 78; Alfa Romeo Sprint 78-77; Alfa Romeo TZ 2 67; Alfa Romeo TZ 65; Austin America 71-68; Austin Healey Sprite 70-65; Austin Marina 75-73; Chevrolet LUV 78-75; Chevrolet Luv Pickup 74-72; Fiat 1100 67-65; Fiat 124 78-66; Fiat 13178-75; Fiat 1500 67-65; Ford Anglia 68-59; Ford Consul 64-62; Ford Cortina 70-63; Ford Zephyr 63-58; Hillman Husky 66-55; Hillman Minx 66-47; Lotus Elan 71-62; Lotus Elite 66-62; MG 1100 67-62; MG 1300 69-68; MG Magnette 68-59; MG MGA 62-56; MG MGB 67-62; MG MGC 69-68; MG Midget 60; MG Midget 77-62; MG TC 49-45; MG TD 53-49; MG TDC 53-51; MG TF 55-54; MG YA 50-47; MG YB 53-51; MG YC 50-47; MG ZA 56-54; MG ZB 58-57; Morris Minor 71-56; Morris Oxford 71-59; Plymouth Cricket 74-71; Simca 1000 68-63; Simca 1000S 68-63; Simca 5 68-63; Simca Ariane 61-59; Simca Aronde 61-57; Simca Vedette 61-57; Triumph 2000 67; Triumph GT6 73-67; Triumph Herald 70-61;

* Lube Fitting in Bearing Cap

Part#	Application
1-0221 (Cont.)	Triumph Spitfire 77-63; Triumph TR7 77; Vauxhall Fourteen 49; Vauxhall Ten 49; Vauxhall Twelve 49; Vauxhall Velox 49; Vauxhall Victor 63-57; Vauxhall Wyvern 49; Volvo 122 68-60; Volvo 142 74-67; Volvo 144 74-67; Volvo 145 74-68; Volvo 1800 73-61; Volvo 242 77-75; Volvo 244 77-75; Volvo 245 77-75; Volvo 262 76; Volvo 264 77-76; Volvo 265 77-76
1-0248	Jeep CJ 5 73-68; Jeep CJ 5A 68; Jeep CJ 6 73-68; Jeep CJ 6A 68; Jeep Jeepster 69-67; Jeep Wagoneer 73-64
1-0278	Chevrolet Blazer 74-69; Chevrolet K10 78-75; Chevrolet K10 Pickup 74-67; Chevrolet K10 Suburban 78-67; Chevrolet K20 78-75; Chevrolet K20 Suburban 78-75; Chevrolet K30 86-79; Chevrolet K5 Blazer 78-75; Chevrolet V30 87; Dodge Dakota 01-87; Dodge Durango 99-98; Dodge Ramcharger 76-74; Dodge W100 76-75; Dodge W200 76-75; Dodge W300 76-75; Ford Bronco 78-70; Ford Bronco II 90; Ford Explorer 96-91; Ford F-100 76-70; Ford F-150 78-76; Ford F-250 78-75; Ford Ranger 97-90; Ford Thunderbird 82-80; GMC Jimmy 78-70; GMC K15 78-75; GMC K15 Suburban 78-75; GMC K15/K1500 Pickup 74-67; GMC K15/K1500 Suburban 74-67; GMC K25 78-75; GMC K25 Suburban 78-75; GMC K3500 79; Jeep Cherokee 01-84; Jeep CJ 5 81-74; Jeep CJ 6 75-74; Jeep CJ 7 81-76; Jeep Comanche 92-86; Jeep Commando 69-66; Jeep Grand Cherokee 01-93; Jeep Grand Cherokee 04-02; Jeep Grand Wagoneer 91-84; Jeep Grand Wagoneer 93; Jeep J 10 88-74; Jeep J20 88-74; Jeep Scrambler 81; Jeep TJ 06-97; Jeep Wagoneer 90-84; Jeep Wrangler 06-97; Lincoln Continental 87-82; Lincoln Mark VII 92-84; Lincoln Versailles 80-79; Mazda B2300 96-95; Mazda B3000 97-94; Mazda B4000 97-94; Mazda Navajo 94-91; Mercury Cougar 82-80; Oldsmobile Bravada 94-91; Plymouth Trailduster 81-74
1-0297	Chevrolet Blazer 74-72; Chevrolet Blazer 91-87; Chevrolet K10 86-75; Chevrolet K10 Pickup 74-72; Chevrolet K10 Suburban 86-72; Chevrolet K20 86-75; Chevrolet K20 Pickup 74-72; Chevrolet K20 Suburban 86-72; Chevrolet K5 Blazer 86-75; Chevrolet V10 87; Chevrolet V10 Suburban 88-87; Chevrolet V1500 Suburban 91-89; Chevrolet V20 87; Chevrolet V20 Suburban 88-87; Chevrolet V2500 Suburban 91-89; Dodge Ram 1500 01-94; Dodge Ram 2500 01-94; Dodge Ramcharger 93-74; Dodge W100 77-75; Dodge W100 89-86; Dodge W100 Pickup 74-72; Dodge W150 93-77; Dodge W200 80-75; Dodge W200 Pickup 74-72; Dodge W250 93-81; Dodge W300 80-75; Dodge W350 93-81; Ford Bronco 96-78; Ford Bronco II 90; Ford Explorer 94-91; Ford F-100 76-72; Ford F-150 96-76; Ford F-250 98-75; Ford F-350 81-80; Ford Ranger 97-90; GMC Jimmy 91-72; GMC K15 78-75; GMC K15 Suburban 78-75; GMC K15/K1500 Suburban 74-72; GMC K1500 86-79; GMC K1500 Suburban 86-79; GMC K25 78-75; GMC K25 Suburban 78-75; GMC K25/K2500 Pickup 74-72; GMC K25/K2500 Suburban 74-72; GMC K2500 86-79; GMC K2500 Suburban 86-79; GMC V1500 Suburban 91-88; GMC V2500 87; GMC V2500 Suburban 91-87; International 100 74; International Scout II 80-74; Jeep Cherokee 01-88; Jeep Cherokee 83-74; Jeep CJ 5 83-82; Jeep CJ 7 86-82; Jeep Grand Cherokee 01-93; Jeep Grand Wagoneer 91-84; Jeep Grand Wagoneer 93; Jeep J 10 88-74; Jeep J20 88-74; Jeep TJ 06-97; Jeep Wagoneer 83-74; Jeep Wagoneer 90-88; Jeep Wrangler 12-97; Jeep Wrangler 95-87; Mazda B2300 96-95; Mazda B3000 97-94; Mazda B4000 97-94; Mazda Navajo 94-91; Plymouth Trailduster 81-74
1-0298*	Chevrolet Blazer 74-72; Chevrolet Blazer 91-87; Chevrolet K10 86-75; Chevrolet K10 Pickup 74-72; Chevrolet K10 Suburban 86-72; Chevrolet K20 86-75; Chevrolet K20 Pickup 74-73; Chevrolet K20 Suburban 86-73; Chevrolet K5 Blazer 86-75; Chevrolet V10 87; Chevrolet V10 Suburban 88-87; Chevrolet V1500 Suburban 91-89; Chevrolet V20 87; Chevrolet V20 Suburban 88-87; Chevrolet V2500 Suburban 91-89; Chevrolet V30 88; Chevrolet V3500 89; Dodge Ram 1500 01-94; Dodge Ram 2500 99-94; Dodge Ramcharger 93-74; Dodge W100 77-75; Dodge W100 89-84; Dodge W100 Pickup 74-72; Dodge W150 93-77; Dodge W200 80-75; Dodge W200 Pickup 74-72; Dodge W250 93-81; Dodge W300 Pickup 74-73; Ford Bronco 96-78; Ford Bronco II 90; Ford Explorer 94-91; Ford F-100 76-70; Ford F-150 85-76; Ford F-250 98-75; Ford F-350 81-80; Ford Ranger 97-90; GMC Jimmy 72-70; GMC Jimmy 91-78; GMC K15 78-77; GMC K15 Suburban 78-75; GMC K15/K1500 Suburban 74-72; GMC K1500 86-79; GMC K1500 Suburban 86-79; GMC K25 78-75; GMC K25 Suburban 78-75; GMC K25/K2500 Pickup 74-72; GMC K2500 86-79; GMC K2500 Suburban 91-87; GMC K2500 Suburban 86-79; GMC V1500 87; GMC V1500 Suburban 91-87; GMC V2500 87; GMC V2500 Suburban 91-87; International Scout II 80-74; Jeep Cherokee 01-74; Jeep Grand Cherokee 99-94; Jeep Grand Wagoneer 91-84; Jeep J 10 88-74; Jeep J20 88-74; Jeep TJ 06-97; Jeep Wagoneer 90-75; Jeep Wrangler 11-97; Jeep Wrangler 95-93; Mazda B2300 96-95; Mazda B3000 97-94; Mazda B4000 97-94; Mazda Navajo 94-91; Plymouth Trailduster 81-74
1-0300*	Alfa Romeo 164 93-91; Alfa Romeo Alfetta 77-75; Alfa Romeo Berlina 71; Alfa Romeo Giulia Sprint 68-67; Alfa Romeo GT Veloce 74-69; Alfa Romeo GTV-6 86-81; Alfa Romeo Milano 89-87; Alfa Romeo Spider 93-70; Alfa Romeo Sport 79-78; Alfa Romeo Sprint 79-78; American Motors American 68; Austin America 72-70; Austin Marina 75-73; Chevrolet LUV 82-75; Chevrolet Luv Pickup 74-72; Fiat 124 83-74; Fiat 131 78-75; Fiat Brava 81-78; Isuzu Pickup 87-81; Isuzu Trooper 87-84; MG MGB 81-62; MG Midget 79-62; Plymouth Cricket 74-71; Triumph GT6 73-67; Triumph Spitfire 80-63; Triumph TR7 81-75; Triumph TR8 81-80; Volvo 122 68-60; Volvo 242 84-75; Volvo 244 84-75; Volvo 245 84-75; Volvo 262 76; Volvo 262 81-78; Volvo 264 82-76; Volvo 265 81-76
1-0350	Chevrolet Chevette 87-76; Pontiac Acadian 87-81; Pontiac T1000 87-81
1-0421	Land Rover Discovery 04-00; Land Rover Freelander 05-02
1-0430*	Jaguar Vanden Plas 89-88; Jaguar XJ 12 89-88; Jaguar XJ 6 89-88; Jaguar XJS 89-88; Nissan 200SX 88-78; Nissan 240SX 98-89; Nissan 280Z 78; Nissan 280ZX 83-79; Nissan 720 86; Nissan 810 81-77; Nissan D21 89-86; Subaru DL 89-85; Subaru GL 89-85; Subaru GL-10 89-85; Subaru Legacy 91-90; Subaru Loyale 93-90; Subaru RX 89-86; Subaru SVX 96-92; Subaru XT 90-85; Toyota Camry 91-88; Toyota Celica 86-81; Toyota Corolla 84-80; Toyota Cressida 88-85; Toyota Previa 94-91; Toyota Van 89-87
1-0431*	BMW 535i 93-89; BMW 735i 92-87; BMW 750iL 94-88; BMW M5 93-91; Mazda 929 95-92; Mazda B2000 84-79; Mazda B2000 87-86; Mazda B2200 93-82; Mazda B2600 93-87; Mazda MPV 95-89; Mazda RX-7 91-87
1-0436*	Kia Sorento 06-03
1-0439*	Chevrolet Equinox 06-05; Pontiac Torrent 06; Saturn Vue 07-02
1-0443*	American Motors Gremlin 75; American Motors Matador 75; American Motors Pacer 75; Ford Aerostar 97-90; Ford Bronco II 85-84; Ford Ranger 89-83; Ford Tempo 91-87; GMC Syclone 91; GMC Typhoon 93-92; Hyundai Pony 87-84; Hyundai Stellar 87-85; Mercury Topaz 91-87; Oldsmobile Bravada 94-91; Pontiac 6000 90-89; Subaru Legacy 99
1-0445	Buick Rainier 07-04; Chevrolet Astro 05-90; Chevrolet Blazer 05-95; Chevrolet Blazer 88; Chevrolet S10 04-83; Chevrolet S10 Blazer 94-83; Chevrolet Trailblazer 09-02; Chevrolet Trailblazer EXT 06-02; GMC Envoy 09-02; GMC Envoy XL 06-02; GMC Envoy XUV 05-04; GMC Jimmy 05-92; GMC S15 90-83; GMC S15 Jimmy 91-83; GMC Safari 05-90; GMC Sonoma 04-91; GMC Syclone 91; GMC Typhoon 93-92; Hummer H3 10-06; Hummer H3T 10-09; Isuzu Ascender 07-03; Isuzu Hombre 00-98; Oldsmobile Bravada 04-98; Saab 9-7x 05; Saab 9-7x 09-08

* Lube Fitting in Bearing Cap

Part#	Application
1-0449*	INFINITI QX4 03-97; Nissan 720 86; Nissan D2189-86; Nissan Pathfinder 04-87
1-1475	Buick Century 81-75; Buick Electra 81-75; Buick Estate Wagon 81-70; Buick Gran Sport 67-65; Buick LeSabre 81-75; Buick Regal 81-75; Buick Riviera 78-75; Buick Sportwagon 72-64; Cadillac Commercial Chassis 81-75; Cadillac DeVille 81-75; Cadillac Fleetwood 81-75; Cadillac Seville 79-76; Chevrolet Bel Air 75; Chevrolet Bel Air 81; Chevrolet Blazer 74-72; Chevrolet C10 78; Chevrolet C10 Suburban 78; Chevrolet C20 81; Chevrolet C20 Suburban 81; Chevrolet Camaro 81-76; Chevrolet Caprice 81-75; Chevrolet Chevelle 73-71; Chevrolet El Camino 81-76; Chevrolet G10 81-78; Chevrolet G20 81-75; Chevrolet G20 Van 74-67; Chevrolet G30 81-78; Chevrolet Impala 81-75; Chevrolet K10 81-78; Chevrolet K10 Suburban 81-78; Chevrolet K20 81-77; Chevrolet K20 Suburban 81-77; Chevrolet K30 81-80; Chevrolet K5 Blazer 81-75; Chevrolet Laguna 76-75; Chevrolet Malibu 81-73; Chevrolet Monte Carlo 81-75; Chevrolet P20 Series 67; Chevrolet P20 Van 74-68; Chevrolet P30 79; Dodge Ramcharger 81-74; Dodge W100 77-75; Dodge W150 81-77; Dodge W200 80-75; Dodge W250 81; Dodge W300 80-75; Dodge W350 81; Ford F-150 81; Ford LTD II 79; Ford Thunderbird 79; GMC C1500 81-79; GMC C25 78; GMC C2500 Suburban 81; GMC Caballero 81-78; GMC G15 78; GMC G1500 81-79; GMC G25 78-75; GMC G25/G2500 Van 74-67; GMC G2500 81-79; GMC G35 78-76; GMC G3500 80-79; GMC Jimmy 80-78; GMC K15 78-77; GMC K15 Suburban 78-77; GMC K1500 80-79; GMC K1500 Suburban 80-79; GMC K25 78-77; GMC K25 Suburban 78-77; GMC K2500 80-79; GMC K2500 Suburban 80-79; GMC K3500 80; GMC P25/P2500 Van 74-67; GMC P2500 80; GMC Sprint 77-71; Lincoln Continental 79-77; Mercury Cougar 79; Oldsmobile 442 71-64; Oldsmobile 98 80-75; Oldsmobile Custom Cruiser 80-75; Oldsmobile Cutlass 80-64; Oldsmobile Cutlass Calais 78; Oldsmobile Cutlass Cruiser 80; Oldsmobile Cutlass Salon 80-75; Oldsmobile Cutlass Supreme 86-75; Oldsmobile Cutlass Supreme 80; Oldsmobile Cutlass Tiara 76; Oldsmobile Delta 88 80-75; Oldsmobile Vista Cruiser 75; Plymouth Trailduster 80-74; Pontiac Bonneville 80-75; Pontiac Catalina 80-75; Pontiac Firebird 68-67; Pontiac Firebird 80-75; Pontiac Grand Am 75; Pontiac Grand Am 80-78; Pontiac Grand LeMans 80-75; Pontiac Grand Prix 80-75; Pontiac GTO 73-64; Pontiac LeMans 80-63; Pontiac Parisienne 80-76; Pontiac Tempest 70-61; Pontiac Ventura 61-60; Pontiac Ventura 77
1-1516	Chrysler Conquest 89-87; Dodge Challenger 83-78; Dodge Colt 80-78; Dodge Conquest 86-84; Dodge D50 82-79; Dodge Power Ram 50 86-83; Dodge Raider 89-87; Dodge Ram 50 93-83; Mitsubishi Mighty Max 96-83; Mitsubishi Montero 06-00; Mitsubishi Montero 89-83; Mitsubishi Montero 98-94; Mitsubishi Montero Sport 04-97; Mitsubishi Outlander 06-03; Plymouth Arrow 80-79; Plymouth Arrow Pickup 82-79; Plymouth Sapporo 83-78
1-1557*	Chevrolet Tracker 04-98; Chevrolet Tracker 91-89; Dodge Challenger 83-81; Dodge Colt 80-71; Dodge Colt 91-85; Dodge D50 82-79; Dodge Power Ram 50 86-83; Dodge Raider 89-87; Dodge Ram 50 93-83; Eagle 2000 GTX 93-91; Eagle Summit 95-92; Eagle Talon 95-90; Geo Tracker 97-89; Mitsubishi Mighty Max 96-83; Mitsubishi Montero 02-99; Mitsubishi Montero 96-83; Mitsubishi Montero Sport 04-97; Mitsubishi Outlander 06-03; Mitsubishi Van 87; Plymouth Arrow 80-76; Plymouth Arrow Pickup 82-79; Plymouth Sapporo 79-78; Plymouth Sapporo 83-81; Pontiac Sunrunner 97-95; Suzuki Grand Vitara 05-99; Suzuki Samurai 95-85; Suzuki Sidekick 98-89; Suzuki Vitara 04-99; Suzuki X-90 98-96; Suzuki XL-7 06-02
1-1604*	Mazda GLC 81-77; Mazda Mizer 77-76
1-1610*	Ford Courier 82-72; Mazda 929 95; Mazda B1600 76-72; Mazda B1800 78-77; Mazda B2000 84-79; Mazda B2000 87-86; Mazda B2200 93-82; Mazda B2600 93-87; Mazda MPV 95-89
1-1612*	Lexus GX460 20-10; Lexus GX470 09-03; Lexus LX450 97-96; Lexus LX470 07-98; Lexus LX570 11-08; Lexus LX570 20-13; Toyota 4Runner 20-84; Toyota Camry 88-83; Toyota Crown 72-71; Toyota FJ Cruiser 14-07; Toyota Land Cruiser 11-91; Toyota Land Cruiser 20-13; Toyota Pickup 95-79; Toyota Previa 97-91; Toyota Sequoia 04-01; Toyota Supra 93-86; Toyota T100 98-93; Toyota Tacoma 04-95; Toyota Tundra 06-00
1-1875	American Motors Ambassador 66-62; American Motors American 67-65; Buick Special 63-61; Ford Consul 60-56; Ford Country Sedan 60-50; Ford Country Squire 60-50; Ford Crestline 54-50; Ford Custom 300 60-57; Ford Custom 52-49; Ford Custom 57; Ford Customline 56-52; Ford Del Rio Wagon 58-57; Ford Deluxe 51-49; Ford Fairlane 60-55; Ford Falcon 68-65; Ford Galaxie 60-59; Ford Mainline 56-52; Ford Mustang 66-64; Ford Ranch Wagon 60-50; Ford Ranchero 60-57; Jeep Wagoneer 65-64; Oldsmobile Cutlass 63-61; Oldsmobile Deluxe 88 53-51; Oldsmobile F85 63-61; Oldsmobile Jetfire 63-62; Oldsmobile Series 98 42-41; Oldsmobile Series 98 49-46; Pontiac Catalina 55-50; Pontiac Safari 55; Pontiac Streamliner 42-41; Pontiac Streamliner 52-46; Pontiac Torpedo 48-46
1-2075	Alfa Romeo 1900 58-54; Alfa Romeo 1900C 57-54; Alfa Romeo 2000 62-58; Alfa Romeo 2600 68-62; Alfa Romeo Berlina 69; Alfa Romeo Berlina 74-71; Alfa Romeo Duetto 1600 68-66; Alfa Romeo Giulia 68-62; Alfa Romeo Giulia Sprint 68-62; Alfa Romeo Giulietta 63-54; Alfa Romeo GT Veloce 69; Alfa Romeo GT Veloce 74-71; Alfa Romeo GTA 68-65; Alfa Romeo GTC 66-64; Alfa Romeo GTV 65; Alfa Romeo GTV 68-67; Alfa Romeo GTZ 64; Alfa Romeo Montreal 75-71; Alfa Romeo Spider 69; Alfa Romeo Spider 78-71; Alfa Romeo Sport 78; Alfa Romeo Sprint 78-77; Alfa Romeo TZ 2 67; Alfa Romeo TZ 65; Austin America 69-68; Austin America 71; Austin Healey Sprite 68-65; Austin Marina 75-73; Chevrolet LUV 78-75; Chevrolet Luv Pickup 74-72; Fiat 1100 67-65; Fiat 124 68-66; Fiat 124 78-71; Fiat 13178-75; Fiat 1500 67-65; Ford Anglia 68-59; Ford Consul 64-62; Ford Cortina 68-63; Ford Zephyr 63-58; Hillman Husky 66-55; Hillman Minx 66-47; Lotus Elan 68-62; Lotus Elan 71-70; Lotus Elite 66-62; MG 1100 67-62; MG 1300 68; MG Magnette 68-59; MG MGA 62-56; MG MGC 68; MG Midget 60; MG Midget 77-62; MG TC 49-45; MG TD 53-49; MG TDC 53-51; MG TF 55-54; MG YA 50-47; MG YB 53-51; MG YT 50-47; MG ZA 56-54; MG ZB 58-57; Morris Minor 68-56; Morris Minor 71-70; Morris Oxford 68-59; Morris Oxford 71-70; Plymouth Cricket 74-71; Simca 1000 68-63; Simca 1000S 68-63; Simca 5 68-63; Simca Ariane 61-59; Simca Aronde 61-57; Simca Vedette 61-57; Triumph 2000 67; Triumph GT6 68-67; Triumph GT6 73-70; Triumph Herald 68-61; Triumph Herald 70; Triumph Spitfire 68-63; Triumph Spitfire 77-70; Triumph TR7 77; Vauxhall Fourteen 49; Vauxhall Ten 49; Vauxhall Twelve 49; Vauxhall Velox 49; Vauxhall Victor 63-57; Vauxhall Wyvern 49; Volvo 122 68-60; Volvo 142 68-67; Volvo 142 74-70; Volvo 144 68-67; Volvo 144 74-70; Volvo 145 68; Volvo 145 74-70; Volvo 1800 68-61; Volvo 1800 73-70; Volvo 242 77-75; Volvo 244 77-75; Volvo 245 77-75; Volvo 262 76; Volvo 264 77-76; Volvo 265 77-76
1-2134	Ford Consul 58-56; Ford Country Sedan 58-50; Ford Country Squire 58-50; Ford Crestline 54-50; Ford Custom 300 58-57; Ford Custom 52-49; Ford Custom 57; Ford Customline 56-52; Ford Del Rio Wagon 58-57; Ford Deluxe 51-49; Ford Fairlane 58-55; Ford Mainline 56-52; Ford Ranch Wagon 58-50; Ford Ranchero 58-57; Pontiac Catalina 55-50; Pontiac Safari 55
1-2173	American Motors American 67-65; Ford Falcon 68-65; Ford Mustang 66-64
1-3650	Ford Consul 60-59; Ford Country Sedan 60-59; Ford Country Squire 60-59; Ford Custom 300 60-59; Ford Fairlane 60-59; Ford Galaxie 60-59; Ford Ranch Wagon 60-59; Ford Ranchero 60-59; International Scout 65-61; Jeep Gadiator 69-68; Jeep Wagoneer 65-64; Jeep Wagoneer 69-68

* Lube Fitting in Bearing Cap

Part#	Application
1-4635	Ford Aerostar 89-86; Ford Consul 62-61; Ford Country Sedan 74-61; Ford Country Squire 74-61; Ford Custom 500 77-64; Ford Custom 72-64; Ford E-100 Econoline 78-75; Ford E-100 Econoline Club Wagon 78-75; Ford E-150 Econoline 78-75; Ford E-150 Econoline Club Wagon 78-75; Ford Elite 76-75; Ford Fairlane 70-61; Ford Fairmont 78; Ford Falcon 70-63; Ford Galaxie 500 74-62; Ford Galaxie 67-61; Ford Gran Torino 76-72; Ford Granada 80-75; Ford LTD 78-65; Ford Maverick 77-70; Ford Mustang 66-64; Ford Mustang 73-68; Ford Mustang II 78-74; Ford Pinto 79-71; Ford Ranch Wagon 74-61; Ford Ranchero 77-61; Ford Ranger 89-88; Ford Torino 76-68; Mercury Bobcat 79-75; Mercury Caliente 67-64; Mercury Colony Park 63-61; Mercury Colony Park 65; Mercury Comet 77-63; Mercury Cougar 71-67; Mercury Cougar 73; Mercury Cougar 76-75; Mercury Cyclone 69-64; Mercury Cyclone 71; Mercury Grand Marquis 78-77; Mercury Marauder 65; Mercury Marquis 78-77; Mercury Monarch 80-75; Mercury Montclair 65; Mercury Montego 76-68; Mercury Monterey 62-61; Mercury Monterey 65
1-5800*	American Motors Ambassador 62-59; American Motors Rebel 60-59; Ford Bronco 69-66; Jeep Gladiator 69-68; Jeep Wagoneer 69-68; Toyota 4Runner 87-84; Toyota Pickup 95-79
1-5900	Dodge D100 Pickup 59-57; Dodge D100 Series 60; Dodge D200 Pickup 59-58; Dodge D300 Pickup 59-58; Dodge D300 Series 60; Dodge W100 Pickup 59-58; Dodge W100 Series 60; Ford Aerostar 89-86; Ford Bronco 77-70; Ford Consul 62-61; Ford Country Sedan 74-61; Ford Country Squire 74-61; Ford Country Squire 89-87; Ford Custom 500 77-64; Ford Custom 72-64; Ford E-100 Econoline 78-75; Ford E-100 Econoline Club Wagon 78-75; Ford E-150 Econoline 78-75; Ford E-150 Econoline Club Wagon 78-75; Ford Elite 76-75; Ford Fairlane 70-61; Ford Fairmont 83-78; Ford Falcon 70-63; Ford Galaxie 500 74-62; Ford Galaxie 67-61; Ford Gran Torino 76-72; Ford Granada 82-75; Ford LTD 86-65; Ford LTD Crown Victoria 89-87; Ford Maverick 77-70; Ford Mustang 73-64; Ford Mustang 86-79; Ford Mustang II 78-74; Ford Pinto 80-71; Ford Ranch Wagon 74-61; Ford Ranchero 77-61; Ford Ranger 89-83; Ford Thunderbird 88-80; Ford Torino 76-68; International 100 74; International 1000A 66; International 1000B 69-67; International 1000C 69-68; International 1000D 70-69; International 1010 73-71; International 1000A 66; International 1100B 69-67; International 1100C 69-68; International 1100D 70-69; International 1110 73-71; International 1200A 66; International 1200B 69-67; International 1200C 69-68; International 1200D 70-69; International 1210 73-71; International 1300A 66; International 1300B 69-67; International 1300C 69-68; International 1300D 70-69; International 1310 73-71; International 150 75; International 200 75-74; International M200 72-66; International MA200 71-67; International Scout 71-66; International Scout II 80-71; International Travelall 75; Lincoln Continental 80; Lincoln Continental 87-82; Lincoln Mark VI 83-80; Lincoln Mark VII 92-84; Mercury Bobcat 80-75; Mercury Caliente 67-64; Mercury Capri 86-79; Mercury Colony Park 63-61; Mercury Colony Park 65; Mercury Colony Park 89-87; Mercury Comet 77-63; Mercury Cougar 71-67; Mercury Cougar 73; Mercury Cougar 88-80; Mercury Cyclone 69-64; Mercury Cyclone 71; Mercury Grand Marquis 89-77; Mercury Marauder 65; Mercury Marquis 86-77; Mercury Monarch 80-75; Mercury Montclair 65; Mercury Montego 76-68; Mercury Monterey 62-61; Mercury Monterey 65; Mercury Zephyr 83-78
1-6300*	American Motors Concord 79-78; American Motors Gremlin 78-75; American Motors Pacer 79-75; American Motors Spirit 79; Chrysler Cordoba 79-75; Chrysler LeBaron 79-77; Chrysler New Yorker 76-75; Chrysler New Yorker 79-78; Chrysler Newport 79-75; Dodge A100 70-64; Dodge A100 Pickup 70-67; Dodge A100 Truck 70-64; Dodge Aspen 79-76; Dodge B100 79-75; Dodge B100 Van 74-71; Dodge B200 79-75; Dodge B200 Van 74-71; Dodge B300 79-75; Dodge B300 Van 74-71; Dodge CB300 79-73; Dodge Charger 78-75; Dodge Coronet 76-75; Dodge D100 79-75; Dodge D100 Pickup 74-68; Dodge D100 Series 67-61; Dodge D150 79-77; Dodge D200 79-75; Dodge D200 Pickup 74-68; Dodge D200 Series 67-60; Dodge D300 79-75; Dodge D300 Pickup 59-57; Dodge D300 Pickup 74-68; Dodge D300 Series 67-60; Dodge Dart 76-75; Dodge Diplomat 79-77; DODGE M400 73; Dodge Magnum 79-78; Dodge MB300 74-72; Dodge Monaco 78-75; Dodge P200 72-61; Dodge P200 Van 64-61; Dodge P200 Van 74-67; Dodge Ramcharger 78-74; Dodge RD200 78; Dodge Royal Monaco 77-75; Dodge W100 77-75; Dodge W100 Pickup 74-68; Dodge W100 Series 67-61; Dodge W150 78-77; Dodge W200 78-75; Dodge W200 Pickup 74-68; Dodge W200 Series 67-61; Dodge W300 78-75; Jeep Cherokee 78-74; Jeep Commando 73-67; Jeep Jeepster 71-67; Jeep Wagoneer 69-63; Jeep Wagoneer 78-75; Plymouth Duster 76-75; Plymouth Fury 78-75; Plymouth Gran Fury 77-75; Plymouth PB100 78-75; Plymouth PB100 Van 74; Plymouth PB200 78-75; Plymouth PB300 78-75; Plymouth PB300 Van 74; Plymouth Road Runner 75; Plymouth Trailduster 78-74; Plymouth Valiant 76-75; Plymouth Volare 78-76
1-6301	American Motors AMX 80-78; American Motors Concord 81-78; American Motors Eagle 81-80; American Motors Gremlin 76-75; American Motors Hornet 75; American Motors Matador 78-75; American Motors Pacer 80-76; American Motors Spirit 81-79; Chrysler Cordoba 83-75; Chrysler Fifth Avenue 89-83; Chrysler Imperial 64-58; Chrysler LeBaron 81-77; Chrysler LeBaron 88-84; Chrysler New Yorker 82-58; Chrysler New Yorker 88-84; Chrysler Newport 81-58; Chrysler Town & Country 88-85; Chrysler Town & Country 91-90; Dodge 600 88-84; Dodge A100 69-64; Dodge A100 Pickup 70-67; Dodge A100 Truck 70-64; Dodge A108 Van 70-67; Dodge Aspen 80-76; Dodge B100 80-75; Dodge B100 Van 74-71; Dodge B150 94-81; Dodge B200 80-75; Dodge B200 Van 74-71; Dodge B250 93-81; Dodge B300 80-75; Dodge B300 Van 74-71; Dodge B350 94-81; Dodge Caravan 90-89; Dodge CB300 80-73; Dodge Challenger 74-70; Dodge Charger 78-66; Dodge Charger 87; Dodge Coronet 59-58; Dodge Coronet 76-65; Dodge D100 79-75; Dodge D100 89-86; Dodge D100 Pickup 74-68; Dodge D100 Series 67-61; Dodge D150 93-77; Dodge D200 80-75; Dodge D200 Pickup 74-68; Dodge D200 Series 67-60; Dodge D250 93-81; Dodge D300 80-75; Dodge D300 Pickup 74-68; Dodge D300 Series 67-61; Dodge D350 93-81; Dodge Dakota 99-87; Dodge Dart 76-60; Dodge Daytona 91-84; Dodge Diplomat 89-77; Dodge Grand Caravan 90-89; Dodge Lancer 89-85; Dodge M300 74-68; Dodge M350 74; Dodge M375 73-71; Dodge M400 74-73; Dodge Magnum 79-78; Dodge Mirada 83-80; Dodge Monaco 78-65; Dodge Omni 90-84; Dodge Polara 73-60; Dodge Ram 3500 96-94; Dodge Ramcharger 93-74; Dodge RD200 80-78; Dodge Royal Monaco 77-75; Dodge Shadow 91-87; Dodge Spirit 91-89; Dodge St. Regis 81-79; Dodge W100 77-75; Dodge W100 89-86; Dodge W100 Pickup 74-68; Dodge W100 Series 67-61; Dodge W150 93-77; Dodge W200 80-75; Dodge W200 Pickup 74-68; Dodge W200 Series 67-61; Dodge W250 93-81; Dodge W300 80-75; Dodge W350 93-81; Jeep Cherokee 80-74; Jeep Wagoneer 80-66; Plymouth Acclaim 92-89; Plymouth Barracuda 74-64; Plymouth Belvedere 71-58; Plymouth Caravelle 89-84; Plymouth Duster 76-70; Plymouth Fury 78-58; Plymouth Gran Fury 77-72; Plymouth Gran Fury 89-80; Plymouth Grand Voyager 90-89; Plymouth GTX 71-68; Plymouth Horizon 90-84; Plymouth Road Runner 75-68; Plymouth Satellite 74-65; Plymouth Scamp 76-71; Plymouth Sundance 92-87; Plymouth Trailduster 81-74; Plymouth Valiant 76-60; Plymouth Volare 80-76; Plymouth Voyager 90-89
2-0020	Toyota Land Cruiser 18-16; Toyota Land Cruiser 97-74; Toyota Sequoia 07-05
2-0052*	Bentley Continental 65-59; Bentley S2 Series 61-59; Bentley S3 Series 65-62; Chevrolet 3C 59; Chevrolet 3D 59; Chevrolet 3E 59; Chevrolet 3F 59; Chevrolet 3G 59; Chevrolet Blazer 74; Chevrolet C10 76-75; Chevrolet C10 Panel 67-60; Chevrolet C10 Pickup 74-60; Chevrolet C10 Suburban 76-67; Chevrolet C20 76-75; Chevrolet C20 Panel 67; Chevrolet C20 Pickup 74-60; Chevrolet C20 Suburban 76-67; Chevrolet C30 76-75; Chevrolet C30 Panel 66-60; Chevrolet C30 Pickup 74-60;

* Lube Fitting in Bearing Cap

Part#	Application
2-0052* (Cont.)	Chevrolet Corvette 76-75; Chevrolet G20 76; Chevrolet G30 76-75; Chevrolet K10 Pickup 66-64; Chevrolet K20 76-75; Chevrolet K20 Pickup 72-60; Chevrolet K20 Suburban 76-68; Chevrolet Laguna 76; Chevrolet Malibu 76; Chevrolet Monte Carlo 76; Chevrolet P10 76-75; Chevrolet P20 76-75; Chevrolet P20 Series 66-60; Chevrolet P30 76-75; Chevrolet P30 Series 67-60; Chevrolet P30 Van 74-68; Daimler DK400 59-56; Dodge W100 Pickup 70-68; Dodge W100 Series 67-61; Dodge W200 Pickup 71-68; Dodge W200 Series 67-61; Ford E-300 Econoline 74-69; Ford F-100 68-65; Ford F-250 76-60; Ford F-350 75-68; Ford P-350 74-70; GMC 1000 Series 65-60; GMC 100-24 54; GMC 150 53-51; GMC 150 59-55; GMC 1500 Series 65-60; GMC 150-22 53-51; GMC 150-24 53; GMC C15 75; GMC C15 Suburban 75; GMC C15/C1500 Pickup 74-67; GMC C15/C1500 Suburban 74; GMC C25 75; GMC C25 Suburban 75; GMC C25/C2500 Pickup 74-67; GMC C35 75; GMC C35/C3500 Pickup 74-67; GMC G35 75; GMC G35/G3500 Van 74-70; GMC Jimmy 75-73; GMC K15 75; GMC K15/K1500 Pickup 74-66; GMC K15/K1500 Suburban 69-67; GMC K25 75; GMC K25 Suburban 75; GMC K25/K2500 Pickup 69-67; GMC K25/K2500 Pickup 74-73; GMC P15 75; GMC P25 75; GMC P35 75; GMC P35/P3500 Van 74-67; International 1000A 66; International 1000B 67; International 1000C 68; International 1000D 69; International 1200A 66; International 1200B 67; International 1200C 68; International 1200D 69; International 900A 67-66; Oldsmobile 442 67-64; Oldsmobile Outlass 67-66; Pontiac Bonneville 75; Pontiac Firebird 75; Rolls-Royce Camargue 75; Rolls-Royce Corniche 75-71; Rolls-Royce Phantom 70-59; Rolls-Royce Silver Cloud 65-55; Rolls-Royce Silver Dawn 54-50; Rolls-Royce Silver Shadow 75-66; Rolls-Royce Silver Wraith 58-50; Rover 2000 73-70; Rover 3500S 74-70
2-0053 2-0053G 2-0053P	AM General Hummer 01-00; Buick Electra 85-82; Buick Estate Wagon 83-82; Buick LeSabre 85-82; Buick Regal 87-82; Cadillac DeVille 84-82; Cadillac Escalade 14-07; Cadillac Escalade 23-21; Cadillac Escalade ESV 14-08; Cadillac Escalade ESV 23-21; Cadillac Escalade EXT 13-09; Chevrolet Astro 03-85; Chevrolet Avalanche 13-07; Chevrolet Blazer 05-95; Chevrolet Blazer 74-69; Chevrolet Blazer 91-87; Chevrolet C10 86-75; Chevrolet C10 Panel 67-60; Chevrolet C10 Pickup 74-61; Chevrolet C10 Suburban 86-60; Chevrolet C1500 99-88; Chevrolet C1500 Suburban 99-94; Chevrolet C20 86-75; Chevrolet C20 Panel 67; Chevrolet C20 Pickup 74-62; Chevrolet C20 Suburban 86-68; Chevrolet C2000 00-88; Chevrolet C2500 Suburban 99-92; Chevrolet C30 86-75; Chevrolet C30 Panel 66-60; Chevrolet C30 Pickup 74-61; Chevrolet C3500 00-88; Chevrolet C4500 Kodiak 09-05; Chevrolet C5500 Kodiak 09-05; Chevrolet Camaro 84-82; Chevrolet Caprice 84-82; Chevrolet Colorado 18-15; Chevrolet Colorado 23-20; Chevrolet Corvette 82-63; Chevrolet Corvette 96-84; Chevrolet Express 1500 14-96; Chevrolet Express 2500 10-96; Chevrolet Express 3500 10-96; Chevrolet G10 84-78; Chevrolet G20 81-76; Chevrolet G20 84; Chevrolet G30 96-75; Chevrolet Impala 85-80; Chevrolet Impala 96-94; Chevrolet K10 78; Chevrolet K10 86-82; Chevrolet K10 Pickup 66-60; Chevrolet K10 Suburban 66-60; Chevrolet K10 Suburban 78; Chevrolet K10 Suburban 88-87; Chevrolet K10 Suburban 86-82; Chevrolet K1500 99-88; Chevrolet K1500 Suburban 99-97; Chevrolet K20 86-75; Chevrolet K20 Pickup 74-61; Chevrolet K20 Suburban 86-61; Chevrolet K2500 00-88; Chevrolet K2500 Suburban 99-92; Chevrolet K30 86-77; Chevrolet K3500 00-88; Chevrolet K5 Blazer 86-82; Chevrolet Laguna 76; Chevrolet Malibu 83-76; Chevrolet Monte Carlo 88-76; Chevrolet P10 80-75; Chevrolet P10 Series 67-60; Chevrolet P10 Van 74-68; Chevrolet P20 89-75; Chevrolet P20 Series 67-60; Chevrolet P20 Van 74-68; Chevrolet P30 99-75; Chevrolet P30 Series 67-60; Chevrolet P30 Van 74-68; Chevrolet R10 87; Chevrolet R10 Suburban 88-87; Chevrolet R1500 Suburban 91-89; Chevrolet R20 88-87; Chevrolet R20 Suburban 88-87; Chevrolet R2500 89; Chevrolet R2500 Suburban 91-89; Chevrolet R30 88-87; Chevrolet R3500 91-89; Chevrolet Silverado 1500 13-02; Chevrolet Silverado 1500 21-20; Chevrolet Silverado 1500 Classic 07; Chevrolet Silverado 1500 HD 03-01; Chevrolet Silverado 1500 HD 06-05; Chevrolet Silverado 1500 HD Classic 07; Chevrolet Silverado 2500 05-99; Chevrolet Silverado 2500 HD 04-01; Chevrolet Silverado 3500 01; Chevrolet Suburban 1500 14-06; Chevrolet Suburban 15-14; Chevrolet Suburban 23-21; Chevrolet Suburban 2500 08-00; Chevrolet Suburban 66-60; Chevrolet Tahoe 19-08; Chevrolet Tahoe 23-21; Chevrolet Trailblazer 09-06; Chevrolet V10 87; Chevrolet V10 Suburban 88-87; Chevrolet V1500 Suburban 91-89; Chevrolet V20 87; Chevrolet V20 Suburban 88-87; Chevrolet V2500 Suburban 91-89; Chevrolet V30 88-87; Chevrolet V3500 91-89; Dodge Ram 1500 10-04; Dodge Ram 2500 02-00; Dodge Ram 3500 02-97; Dodge Ram 3500 10-08; Dodge Viper 06-92; Dodge Viper 10-08; Dodge Viper 17-15; Dodge W100 Pickup 59-58; Dodge W100 Pickup 71-68; Dodge W100 Series 67-60; Dodge W200 Pickup 71-68; Dodge W200 Series 67-61; Ford Crown Victoria 11-03; Ford E-150 12-03; Ford E-150 14-12; Ford E-150 Club Wagon 05-03; Ford E-150 Econoline 02-97; Ford E-150 Econoline 08-07; Ford E-150 Econoline Club Wagon 02-97; Ford E-250 12-03; Ford E-250 14-12; Ford E-250 Econoline 02-97; Ford E-250 Econoline 79; Ford E-250 Econoline Club Wagon 79; Ford E-250 Super Duty 05-04; Ford E-350 03; Ford E-350 Club Wagon 05-03; Ford E-350 Econoline 02-90; Ford E-350 Econoline 08-07; Ford E-350 Econoline 79; Ford E-350 Econoline Club Wagon 02-90; Ford E-350 Econoline Club Wagon 79; Ford E-350 Super Duty 12-99; Ford E-350 Super Duty 19-12; Ford E-350 Super Duty 21; Ford E-450 Econoline Super Duty 02-00; Ford E-450 Super Duty 19-17; Ford E-450 Super Duty 21; Ford E-550 Econoline Super Duty 02; Ford Econoline 06-99; Ford Excursion 05-00; Ford Expedition 12-97; Ford Expedition 21-12; Ford Explorer 11-06; Ford F-100 69-59; Ford F-150 12-97; Ford F-150 23-12; Ford F-150 Heritage 04; Ford F-250 72-59; Ford F-250 99-75; Ford F-250 HD 97; Ford F-250 Super Duty 10-99; Ford F-350 85-68; Ford F-350 97-87; Ford F-350 Super Duty 19-99; Ford F-550 Super Duty 08-99; Ford Grand Marquis 04-03; Ford Lobo 03-97; Ford Mustang 01-00; Ford Mustang 12-03; Ford Mustang 21-12; Ford P-100 73-70; Ford P-350 74-70; Ford Transit-150 19-15; Ford Transit-250 19-15; Ford Transit-350 19-15; Ford Transit-350 HD 19-15; GMC 1500 Series 65-61; GMC C15 78-75; GMC C15 Suburban 78-75; GMC C15/C1500 Pickup 74-66; GMC C15/C1500 Suburban 74-68; GMC C1500 86-79; GMC C1500 99-88; GMC C1500 Suburban 86-79; GMC C1500 Suburban 94; GMC C1500 Suburban 99-96; GMC C25 78-75; GMC C25 Suburban 78-75; GMC C25/C2500 Pickup 74-66; GMC C25/C2500 Suburban 74-68; GMC C2500 00-88; GMC C2500 86-79; GMC C2500 Suburban 86-79; GMC C2500 Suburban 99-92; GMC C35 78-75; GMC C35 Pickup 66; GMC C35/C3500 Pickup 74-67; GMC C3500 01-88; GMC C3500 86-79; GMC C4500 Topkick 09-05; GMC C5500 Topkick 09-05; GMC Canyon 18-15; GMC Canyon 23-20; GMC Envoy 09-08; GMC G15 78; GMC G1500 84-79; GMC G25 78-76; GMC G2500 81-79; GMC G2500 84; GMC G35 78-75; GMC G3500 96-79; GMC Jimmy 01-95; GMC Jimmy 91-70; GMC K15 78-75; GMC K15 Suburban 78-77; GMC K1500 86-79; GMC K1500 99-88; GMC K1500 Suburban 86-79; GMC K1500 Suburban 99-97; GMC K25 78-75; GMC K25 Pickup 66; GMC K25 Suburban 78-75; GMC K25/K2500 Pickup 74-67; GMC K25/K2500 Suburban 74-68; GMC K2500 00-88; GMC K2500 86-79; GMC K2500 Suburban 86-79; GMC K2500 Suburban 99-92; GMC K35 78-77; GMC K3500 00-79; GMC P15 78-75; GMC P15/P1500 Van 74-67; GMC P1500 80-79; GMC P25 78-75; GMC P25/P2500 Van 74-66; GMC P2500 89-79; GMC P35 78-75; GMC P35/P3500 Van 74-68; GMC P3500 99-79; GMC PB15 Series 66; GMC PB1500 Series 65-63; GMC PB25 Series 66; GMC PB2500 Series 65-63; GMC R1500 87; GMC R1500 Suburban 91-87; GMC R2500 89-87; GMC R2500 Suburban 91-87; GMC R3500 91-87; GMC Safari 03-85; GMC Savana 1500 14-96; GMC Savana 2500 10-96; GMC Savana 3500 10-96; GMC Sierra 1500 13-02; GMC Sierra 1500 21-20; GMC Sierra 1500 Classic 07; GMC Sierra 1500 HD 07-01; GMC Sierra 1500 HD Classic 07; GMC Sierra 2500 04-99; GMC Sierra 2500 HD 04-01; GMC Sierra 3500 01; GMC V1500 87; GMC V1500 Suburban 91-87; GMC V2500 87; GMC V2500 Suburban 91-87; GMC V3500 91-87; GMC W3500 Forward 04-99; GMC Yukon 19-08; GMC Yukon 23-21; GMC Yukon XL 1500 14-07; GMC Yukon XL 19; GMC Yukon XL 23-21; GMC Yukon XL 2500 08-00; Hummer H104-02; Hummer H106; Hummer H2 09-03; Hummer H3 10-06; Hummer H3T 10-09; INFINITI QX56 06-04; INFINITI QX56 13-10; International 1000C 69-68; International 1000D 70-69; International 1100C 69-68; International 1100D 70-69; International 1200C 69-68; International 1200D 70-69; International 150 75; Jeep Gladiator 22-20;

* Lube Fitting in Bearing Cap

Part#	Application
2-0053 2-0053G 2-0053P (Cont.)	Jeep Wrangler 22-07; Jeep Wrangler JK 18; Lincoln Blackwood 03-02; Lincoln Mark LT 08-06; Lincoln Navigator 21-98; Lincoln Town Car 11-04; Mercury Grand Marquis 11-06; Mercury Mountaineer 10-06; Nissan Armada 15-05; Nissan Pathfinder 04; Nissan Pathfinder 11-08; Nissan Pathfinder Armada 04; Nissan Titan 06-04; Oldsmobile 442 67-64; Oldsmobile 98 67-66; Oldsmobile 98 84-82; Oldsmobile Custom Cruiser 85-82; Oldsmobile Cutlass 67-64; Oldsmobile Cutlass 87-85; Oldsmobile Cutlass 98; Oldsmobile Cutlass Calais 84-82; Oldsmobile Cutlass Cruiser 83-82; Oldsmobile Cutlass Salon 87-85; Oldsmobile Cutlass Supreme 67; Oldsmobile Cutlass Supreme 88-82; Oldsmobile Delmont 88 67; Oldsmobile Delta 88 67-66; Oldsmobile Delta 88 85-82; Oldsmobile F85 67-64; Oldsmobile Jetstar 88 67-66; Oldsmobile Starfire 66; Oldsmobile Vista Cruiser 67-64; Pontiac Bonneville 76-75; Pontiac Bonneville 86-79; Pontiac Catalina 81-80; Pontiac Firebird 84-75; Pontiac Grand Prix 87-82; Pontiac Parisienne 84-82; Ram 1500 21-11; Ram 1500 Classic 21-19; Ram 2500 12-11; Ram 3500 12-11; Ram 4500 12-11; Ram 5500 12-11; Rolls-Royce Camargue 79-75; Rolls-Royce Corniche 79-75; Rolls-Royce Silver Shadow 76-75; Rolls-Royce Silver Shadow II 79-77; Rolls-Royce Silver Wraith II 79-77; Rover 2000 73-68; Rover 3500 74-72; Rover 3500 80; Rover 3500S 74-69; Saab 9-7x 09-08; SRT Viper 14-13; Toyota Sequoia 24-08; Toyota Tacoma 23-16; Toyota Tundra 24-07
2-0054 2-0054G 2-0054P	Cadillac Escalade 21-15; Cadillac Escalade ESV 21-15; Chevrolet Avalanche 2500 06-02; Chevrolet Blazer 88; Chevrolet Blazer 90-89; Chevrolet Blazer 99-95; Chevrolet C2500 99; Chevrolet C3500 00-91; Chevrolet C3500 04-03; Chevrolet C3500HD 02-91; Chevrolet C4500 Kodiak 09-05; Chevrolet C5500 Kodiak 09-05; Chevrolet Express 2500 21-11; Chevrolet Express 3500 21-00; Chevrolet K2500 00; Chevrolet K3500 00-90; Chevrolet P30 99-79; Chevrolet R25 02-99; Chevrolet R3500 91; Chevrolet Silverado 1500 19-14; Chevrolet Silverado 1500 LD 19; Chevrolet Silverado 2500 05-99; Chevrolet Silverado 2500 HD 21-01; Chevrolet Silverado 2500 HD Classic 07; Chevrolet Silverado 3500 07-01; Chevrolet Silverado 3500 Classic 07; Chevrolet Silverado 3500 HD 21-07; Chevrolet Suburban 20-14; Chevrolet Suburban 2500 06-01; Chevrolet Suburban 2500 13-08; Chevrolet Tahoe 21-18; Chevrolet W3500 Tiltmaster 04-95; Chevrolet W4500 Tiltmaster 04-00; Dodge B150 91-89; Dodge B150 94; Dodge B1500 98-95; Dodge B250 91-89; Dodge B250 94; Dodge B2500 98-95; Dodge B350 91-89; Dodge B3500 98-95; Dodge D250 93-89; Dodge D350 93-89; Dodge Ram 1500 06-04; Dodge Ram 1500 99-94; Dodge Ram 1500 Van 03-95; Dodge Ram 2500 10-94; Dodge Ram 2500 Van 01-96; Dodge Ram 3500 04-94; Dodge Ram 3500 06; Dodge Ram 3500 10-09; Dodge Ram 3500 99-79; Dodge Ram 3500 Van 97-96; Dodge W1500 93-89; Dodge W250 93-88; Dodge W350 93-89; Ford E-300 Econoline 74-68; Ford E-350 Club Wagon 05-04; Ford E-350 Econoline 08-07; Ford E-350 Super Duty 19-04; Ford E-350 Super Duty 21; Ford E-450 Econoline Super Duty 02-99; FORD E-450 Econoline Super Duty Stripped 02-00; Ford E-450 Super Duty 19-03; Ford E-450 Super Duty 21; FORD E-450 Super Duty Stripped Chassis 03; Ford E-550 Econoline Super Duty 02; Ford Econoline Super Duty 99-96; Ford Excursion 05-00; Ford F Super Duty 97-88; Ford F-150 14-11; Ford F-150 18; Ford F-150 23-21; Ford F-250 Super Duty 22-99; Ford F-350 Super Duty 20-99; Ford F-450 Super Duty 18-99; Ford F-450 Super Duty 20; Ford F53 97-88; Ford F-550 Super Duty 18-08; Ford F-550 Super Duty 20; Ford F59 97-88; Ford Lobo 03-97; Ford Transit-150 20-15; Ford Transit-250 20-15; Ford Transit-350 20-15; Ford Transit-350 HD 20-15; GMC C2500 99; GMC C3500 02-91; GMC C3500HD 00; GMC C4500 Topkick 09-05; GMC C5500 Topkick 09-05; GMC K2500 00; GMC K3500 00-92; GMC P35 78; GMC P3500 99-79; GMC R3500 91; GMC Savana 2500 21-11; GMC Savana 3500 21-00; GMC Sierra 1500 19-14; GMC Sierra 1500 Limited 19; GMC Sierra 2500 04-99; GMC Sierra 2500 HD 21-01; GMC Sierra 2500 HD Classic 07; GMC Sierra 3500 07-01; GMC Sierra 3500 Classic 07; GMC Sierra 3500 HD 21-07; GMC W3500 Forward 04-95; GMC W4500 Forward 04-00; GMC Yukon 21-18; GMC Yukon XL 20-15; GMC Yukon XL 2500 06-01; GMC Yukon XL 2500 13-08; INFINITI QX56 13-07; Isuzu NPR 09-95; Isuzu NPR-HD 04-99; Isuzu NPR-HD 09-08; Jaguar 2.4 57-56; Jaguar 3.4 60-57; Jaguar 3.8 66-60; Jaguar 340 67; Jaguar 420 67; Jaguar C-Type 53; Jaguar D-Type 56-54; Jaguar Mark IX 61-59; Jaguar Mark VII 57-53; Jaguar Mark VIII 58-57; Jaguar Mark X 66-62; Jaguar Vanden Plas 89-82; Jaguar XJ 71-69; Jaguar XJ 12 79-73; Jaguar XJ 12 89-81; Jaguar XJ 6 89-72; Jaguar XJS 89-76; Jaguar XK 120 54-53; Jaguar XK 140 57-55; Jaguar XK 150 61-58; Jaguar XKE 74-61; Jaguar XKSS 57; Nissan Armada 15-07; Nissan Frontier 21-17; Nissan Titan 15-07; Nissan Titan 21-17; Nissan Titan XD 18; Ram 2500 20-13; Ram 3500 19-13; Ram 4500 18-11; Ram 5500 18-11
2-0054-1X*	Cadillac Escalade 17-15; Cadillac Escalade ESV 17-15; Chevrolet Avalanche 2500 06-04; Chevrolet C3500 00-91; Chevrolet C3500HD 02-01; Chevrolet Express 2500 17-11; Chevrolet Express 3500 07-02; Chevrolet Express 3500 17-09; Chevrolet K3500 00-92; Chevrolet P30 99-79; Chevrolet R3500 91; Chevrolet Silverado 1500 17-14; Chevrolet Silverado 2500 05-99; Chevrolet Silverado 2500 HD 17-01; Chevrolet Silverado 3500 07-01; Chevrolet Silverado 3500 Classic 07; Chevrolet Silverado 3500 HD 17-07; Chevrolet Suburban 17-16; Chevrolet Suburban 2500 06-01; Chevrolet Suburban 2500 13-09; Dodge B150 94; Dodge B1500 98-95; Dodge B250 94; Dodge B2500 98-95; Dodge B3500 98-95; Dodge D250 93-89; Dodge D350 93-89; Dodge Ram 1500 06-05; Dodge Ram 1500 99-94; Dodge Ram 1500 Van 03-95; Dodge Ram 2500 99-94; Dodge Ram 2500 Van 01-96; Dodge Ram 3500 02-94; Dodge Ram 3500 Van 01-99; Dodge Ram 3500 Van 97-96; Dodge W250 93-88; Dodge W350 93-90; Ford E-300 Econoline 74-69; Ford E-350 Club Wagon 05-04; Ford E-350 Econoline 08-07; Ford E-350 Super Duty 18-04; Ford E-450 Econoline Super Duty 02-00; Ford E-450 Super Duty 17-03; Ford E-550 Econoline Super Duty 02; Ford Econoline Super Duty 99-96; Ford Excursion 05-00; Ford F Super Duty 97-88; Ford F-150 14-11; Ford F-250 Super Duty 18-99; Ford F-350 Super Duty 18-99; Ford F-450 Super Duty 18-09; Ford F53 97-88; Ford F-550 Super Duty 18-09; Ford F59 97-88; Ford Transit-150 18-15; Ford Transit-250 18-15; Ford Transit-350 18-15; Ford Transit-350 HD 18-15; GMC C3500 00-91; GMC K3500 00-92; GMC P3500 99-79; GMC R3500 91; GMC Savana 2500 17-11; GMC Savana 3500 17-02; GMC Sierra 1500 17-14; GMC Sierra 2500 04-99; GMC Sierra 2500 HD 17-01; GMC Sierra 3500 06-01; GMC Sierra 3500 Classic 07; GMC Sierra 3500 HD 17-07; GMC Yukon XL 17-15; GMC Yukon XL 2500 06-02; GMC Yukon XL 2500 13-09; INFINITI QX56 12-10; Jaguar 2.4 57-56; Jaguar 3.4 60-57; Jaguar 3.8 66-60; Jaguar 340 67; Jaguar 420 67; Jaguar C-Type 53; Jaguar D-Type 56-54; Jaguar Mark IX 61-59; Jaguar Mark VII 57-53; Jaguar Mark VIII 58-57; Jaguar Mark X 66-62; Jaguar Vanden Plas 89-82; Jaguar XJ 71-69; Jaguar XJ 12 79-73; Jaguar XJ 12 89-81; Jaguar XJS 89-72; Jaguar XJS 89-76; Jaguar XK 120 54-53; Jaguar XK 140 57-55; Jaguar XK 150 61-58; Jaguar XKE 74-61; Jaguar XKSS 57; Nissan Armada 15-07; Nissan Titan 15-07; Nissan Titan 18-17; Ram 2500 18-13; Ram 3500 18-13; Ram 4500 18-13; Ram 5500 18-13
2-0057	Jeep Gladiator 22-20; Jeep Wrangler 22-07; Jeep Wrangler JK 18
2-0151	Daihatsu Rocky 92-90; Dodge Raider 89; Dodge Ram 50 93-90; Mitsubishi Mighty Max 96-90; Mitsubishi Montero 00-89; Mitsubishi Montero Sport 04-97
2-0317	Acura SLX 99-98; Isuzu Trooper 02-98; Isuzu VehiCROSS 00-99
2-0355 2-0355G 2-0355P	Dodge Dakota 96-92; Dodge Durango 99-98; Dodge Ram 1500 99-94; Dodge Ram 2500 01-94; Dodge Ram 3500 96-94
2-0382*	Suzuki Grand Vitara 13-99; Suzuki Vitara 04; Suzuki XL-7 06-02

* Lube Fitting in Bearing Cap

Part#	Application
2-0383	Acura SLX 99-96; Chevrolet LUV 82-79; Honda Passport 97-94; Isuzu Amigo 94-89; Isuzu Pickup 95-81; Isuzu Rodeo 97-91; Isuzu Trooper 02-84; Isuzu VehiCROSS 01-99
2-0456	Ford Bronco II 90-84; Ford Explorer 94-91; Ford Ranger 97-83; Mazda B2300 96-95; Mazda B3000 97-94; Mazda B4000 97-94; Mazda Navajo 94-91
2-0506*	Hyundai Tucson 09-07; Kia Sorento 06-03; Kia Sportage 02-95; Kia Sportage 10-05; Mazda B2600 93-87; Mazda MPV 95-89
2-0508	Kia Sorento 06-03
2-0521	Chevrolet K30 86-77; Chevrolet V30 88-87; Chevrolet V3500 91-89; Dodge Ram 2500 02-94; Dodge Ram 3500 02-94; Dodge W200 80-75; Dodge W250 81; Dodge W250 93-86; Dodge W300 80-75; Dodge W300 Pickup 74-73; Dodge W350 93-81; Ford Excursion 05-00; Ford F-250 78; Ford F-250 Super Duty 19-99; Ford F-350 79; Ford F-350 97-85; Ford F-350 Super Duty 19-99; Ford F-450 Super Duty 04-99; Ford F-550 Super Duty 04-99; GMC K35 78-77; GMC K3500 86-79; GMC K3500 89-88; GMC V3500 91-87; International 1300A 66; International 1300B 67; International 1300C 68; International 1300D 70-69
2-0599	Dodge Dakota 92-91
2-1175 2-1175G 2-1175P	Chrysler Cordoba 78-75; Chrysler Imperial 75-70; Chrysler LeBaron 78-77; Chrysler New Yorker 78-68; Chrysler Newport 78-68; Dodge Aspen 78-76; Dodge B100 80-75; Dodge B100 Van 74; Dodge B150 81; Dodge B150 88; Dodge B150 94-92; Dodge B1500 98-95; Dodge B200 80-75; Dodge B200 Van 74; Dodge B250 81; Dodge B250 94-92; Dodge B2500 98-95; Dodge B300 80-75; Dodge B350 94-81; Dodge B3500 98-95; Dodge CB300 80-75; Dodge Challenger 72-70; Dodge Charger 78-66; Dodge Coronet 76-66; Dodge D100 79-75; Dodge D100 89-86; Dodge D100 Pickup 74-70; Dodge D150 93-77; Dodge D200 80-75; Dodge D200 Pickup 74-70; Dodge D250 81; Dodge D250 93-89; Dodge D300 80-75; Dodge D300 Pickup 74-72; Dodge D350 81; Dodge D350 93-89; Dodge Dakota 99-90; Dodge Dart 76-68; Dodge Diplomat 78-77; Dodge Durango 99-98; Dodge M300 74-68; Dodge M350 74; Dodge M375 73-71; Dodge M400 74-73; Dodge Magnum 78; Dodge Monaco 78-66; Dodge Polara 73-66; Dodge Ram 1500 99-94; Dodge Ram 1500 Van 01-95; Dodge Ram 2500 01-94; Dodge Ram 2500 Van 01-96; Dodge Ram 3500 01-94; Dodge Ram 3500 Van 01-99; Dodge Ram 3500 Van 97-96; Dodge Ramcharger 93-74; Dodge RD200 80-78; Dodge Royal Monaco 77-75; Dodge W100 77-75; Dodge W150 81-77; Dodge W150 93-89; Dodge W200 80-75; Dodge W250 81; Dodge W250 93-88; Dodge W300 80-75; Dodge W300 Pickup 72; Dodge W350 81; Dodge W350 93-89; Jeep Cherokee 00-88; Jeep Grand Cherokee 01-93; Jeep Grand Wagoneer 93; Jeep Wagoneer 90-88; Plymouth Barracuda 72-68; Plymouth Belvedere 71-66; Plymouth Duster 76-70; Plymouth Fury 78-66; Plymouth Gran Fury 77-72; Plymouth GTX 71-67; Plymouth PB100 80-78; Plymouth PB150 81; Plymouth PB200 80-75; Plymouth PB250 81; Plymouth PB300 80-75; Plymouth PB350 81; Plymouth Road Runner 75-68; Plymouth Satellite 74-66; Plymouth Scamp 76-71; Plymouth Trailduster 81-74; Plymouth Valiant 76-66; Plymouth Volare 80-76
2-1355	Chevrolet Silverado 1500 13-07; Chevrolet Silverado 1500 Classic 07; Dodge Ram 1500 09-06; Dodge Ram 2500 10-03; Dodge Ram 3500 10-04; Dodge Ram 4500 10-08; Dodge Ram 5500 10-08; GMC Sierra 1500 Classic 07; Nissan NV1500 21-12; Nissan NV2500 16-12; Nissan NV3500 16-12
2-1569 2-1569G 2-1569P	Cadillac DeVille 62-57; Cadillac Series 60 Fleetwood 62-57; Cadillac Series 62 58; Cadillac Series 62 62-60; Cadillac Series 75 Fleetwood 62-59; Chevrolet Avalanche 1500 06-02; Chevrolet Bel Air 68-66; Chevrolet Biscayne 68-66; Chevrolet Blazer 94; Chevrolet C10 81-79; Chevrolet C1500 01-88; Chevrolet C1500 Suburban 99-92; Chevrolet Caprice 70-66; Chevrolet Chevelle 68-67; Chevrolet Chevelle 72-71; Chevrolet Colorado 12-04; Chevrolet El Camino 72-65; Chevrolet G10 95-91; Chevrolet G20 78-76; Chevrolet G20 95-91; Chevrolet Impala 68-66; Chevrolet K1500 99-88; Chevrolet K1500 Suburban 99-95; Chevrolet K2500 00-88; Chevrolet K2500 Suburban 99-94; Chevrolet K3500 91-88; Chevrolet Monte Carlo 72-71; Chevrolet P30 79; Chevrolet R1500 1-95; Chevrolet S10 96-94; Chevrolet Silverado 1500 07-99; Chevrolet Silverado 1500 Classic 07; Chevrolet Silverado 99-95; Chevrolet Suburban 1500 06-95; Chevrolet Tahoe 99-95; Chevrolet V30 88; Chevrolet V3500 89; Ford Bronco 87; Ford Bronco 89; Ford F-350 93-87; GMC C1500 81-79; GMC C1500 99-88; GMC C1500 Suburban 81-79; GMC C1500 Suburban 99-92; GMC Canyon 12-04; GMC G1500 95-91; GMC G25 78-75; GMC G2500 95-90; GMC K1500 99-88; GMC K1500 Suburban 99-95; GMC K2500 99-88; GMC K2500 Suburban 99-94; GMC K3500 91-80; GMC P2500 79; GMC P35 78; GMC Sierra 1500 07-99; GMC Sierra 1500 Classic 07; GMC Sierra 1500 HD 01; GMC Sierra C3 01; GMC Sonoma 96-94; GMC Sprint 72-71; GMC V2500 87; GMC V2500 Suburban 88-87; GMC Yukon 97-94; GMC Yukon XL 1500 06-00; Isuzu i-280 06; Isuzu i-290 08-07; Isuzu i-350 06; Isuzu i-370 08-07; Jeep TJ 06-03; Jeep Wrangler 06-03; Oldsmobile 442 70-68; Pontiac Firebird 68-67
2-2275	Chevrolet C1500 94-91; Chevrolet C1500 Suburban 99-94; Chevrolet C2500 99-88; Chevrolet C2500 Suburban 99-92; Chevrolet C3500 99-88; Chevrolet Corvette 97-84; Chevrolet Express 1500 99-96; Chevrolet Express 2500 99-96; Chevrolet Express 3500 99-96; Chevrolet G30 89-88; Chevrolet G30 96-91; Chevrolet K1500 98-88; Chevrolet K2500 99-88; Chevrolet K2500 Suburban 99-92; Chevrolet K3500 99-88; Chevrolet Silverado 1500 HD Classic 07; Chevrolet Silverado 2500 00-99; Chevrolet V30 88; Chevrolet V3500 91-89; Ford E-150 Econoline 99-97; Ford E-150 Econoline Club Wagon 99-97; GMC C1500 91; GMC C1500 94-93; GMC C1500 96; GMC C1500 Suburban 94; GMC C1500 Suburban 99-96; GMC C2500 99-88; GMC C2500 Suburban 99-92; GMC C3500 99-88; GMC G3500 96-91; GMC K1500 98-88; GMC K2500 96-88; GMC K3500 99-88; GMC R2500 89-88; GMC Safari 02-88; GMC Savana 1500 99-96; GMC Savana 2500 99-96; GMC Savana 3500 99-96; GMC Sierra 1500 06; GMC Sierra 1500 Classic 07; GMC Sierra 1500 HD 06-05; GMC Sierra 1500 HD Classic 07; GMC Sierra 2500 04-99; GMC V2500 87; GMC V2500 Suburban 91-87
2-3011 2-3011G 2-3011P	Buick Centurion 73-71; Buick Century 81-73; Buick Commercial Chassis 96-91; Buick Electra 89-61; Buick Estate Wagon 83-70; Buick Invicta 63; Buick LeSabre 90-61; Buick Rainier 07-04; Buick Regal 87-73; Buick Riviera 78-63; Buick Roadmaster 96-91; Buick Skyhawk 80-75; Buick Skylark 72-64; Buick Special 69-64; Buick Wildcat 70-63; Cadillac Brougham 92-87; Cadillac Calais 76-65; Cadillac Commercial Chassis 96-75; Cadillac DeVille 64-53; Cadillac DeVille 84-68; Cadillac Escalade 20-99; Cadillac Escalade ESV 14-03; Cadillac Escalade EXT 13-02; Cadillac Fleetwood 96-65; Cadillac Series 60 Fleetwood 64-50; Cadillac Series 6151-50; Cadillac Series 62 58-52; Cadillac Series 62 64-60; Cadillac Series 75 Fleetwood 64-59; Cadillac Seville 79-76; Chevrolet Astro 05-85; Chevrolet Avalanche 13-07; Chevrolet Avalanche 1500 06-02; Chevrolet Avalanche 2500 06-02; Chevrolet Bel Air 68-66; Chevrolet Bel Air 75-71; Chevrolet Bel Air 81; Chevrolet Biscayne 68-66; Chevrolet Biscayne 72-71; Chevrolet Blazer 05-87; Chevrolet Blazer 74-72; Chevrolet Brookwood 72-71; Chevrolet C10 78; Chevrolet C10 86-82; Chevrolet C10 Suburban 78; Chevrolet C10 Suburban 86-82; Chevrolet C1500 01-88; Chevrolet C20 86-81; Chevrolet C20 Suburban 86-81; Chevrolet Camaro 02-75; Chevrolet Caprice 96-66; Chevrolet Chevelle 68-67; Chevrolet Chevelle 73-71; Chevrolet El Camino 87-65; Chevrolet Express 1500 14-03; Chevrolet Express 2500 05-03; Chevrolet G10 95-78; Chevrolet G20 95-75; Chevrolet G30 90-78; Chevrolet Impala 68-66; Chevrolet Impala 85-71; Chevrolet Impala 96-94; Chevrolet K10 86-78; Chevrolet K10 Suburban 86-78; Chevrolet K1500 99-88; Chevrolet K1500 Suburban 99-92; Chevrolet K20 86-77; Chevrolet K20 Suburban 86-77; Chevrolet K2500 00-88; Chevrolet K2500 Suburban 99-92; Chevrolet K30 86-80; Chevrolet K3500 00-88;

* Lube Fitting in Bearing Cap

Part#	Application
2-3011 2-3011G 2-3011P (Cont.)	Chevrolet K5 Blazer 86-75; Chevrolet Laguna 76-75; Chevrolet LLLV 95-87; Chevrolet Malibu 83-73; Chevrolet Monte Carlo 88-71; Chevrolet P20 89-82; Chevrolet P30 79; Chevrolet P30 84; Chevrolet R10 87; Chevrolet R10 Suburban 88-87; Chevrolet R15 01-95; Chevrolet R1500 Suburban 91-89; Chevrolet R20 88-87; Chevrolet R20 Suburban 88-87; Chevrolet R2500 89; Chevrolet R2500 Suburban 91-89; Chevrolet R30 88-87; Chevrolet R3500 91-89; Chevrolet S10 04-82; Chevrolet S10 Blazer 94-83; Chevrolet Silverado 1500 19-99; Chevrolet Silverado 1500 Classic 07; Chevrolet Silverado 1500 HD 03-01; Chevrolet Silverado 1500 HD 06-05; Chevrolet Silverado 1500 HD Classic 07; Chevrolet Silverado 1500 LD 19; Chevrolet Silverado 2500 04-99; Chevrolet Silverado 2500 HD 20-01; Chevrolet Silverado 2500 HD Classic 07; Chevrolet Silverado 3500 06-01; Chevrolet Silverado 3500 Classic 07; Chevrolet Silverado 3500 HD 20-07; Chevrolet Silverado 99-95; Chevrolet SSR 06-03; Chevrolet Suburban 1500 14-00; Chevrolet Suburban 20-14; Chevrolet Suburban 2500 13-00; Chevrolet Suburban 3500 HD 19-16; Chevrolet Tahoe 20-95; Chevrolet Trailblazer 09-02; Chevrolet Trailblazer EXT 06-02; Chevrolet V10 87; Chevrolet V10 Suburban 88-87; Chevrolet V1500 Suburban 91-89; Chevrolet V20 87; Chevrolet V20 Suburban 88-87; Chevrolet V2500 Suburban 91-89; Chevrolet V30 88-87; Chevrolet V3500 91-89; Chrysler Aspen 09-07; Dodge Durango 00; Dodge Durango 09-04; Dodge Ram 1500 09-06; Dodge Ram 2500 10-03; Dodge Ram 3500 10-00; Dodge Ramcharger 93-74; Dodge W100 77-75; Dodge W100 89-84; Dodge W150 93-77; Dodge W200 80-75; Dodge W250 93-81; Dodge W300 80-75; Dodge W350 93-81; Ford Bronco 87; Ford Bronco 89; Ford F-100 81-79; Ford F-150 81-79; Ford F-350 93-87; Ford LTD II 79; Ford Thunderbird 71-68; Ford Thunderbird 79; GMC C15 78; GMC C15 Suburban 78; GMC C1500 86-79; GMC C1500 99-88; GMC C1500 Suburban 86-82; GMC C25 78; GMC C2500 86-82; GMC C2500 90-89; GMC C2500 Suburban 86-81; GMC C3500 84; GMC Caballero 87-78; GMC Envoy 09-02; GMC Envoy XL 06-02; GMC Envoy XUV 05-04; GMC G15 78; GMC G1500 95-79; GMC G25 78-75; GMC G2500 95-79; GMC G35 78-76; GMC G3500 90-79; GMC Jimmy 05-72; GMC K15 78-77; GMC K15 Suburban 78-77; GMC K1500 86-79; GMC K1500 99-88; GMC K1500 Suburban 86-79; GMC K1500 Suburban 99-92; GMC K25 78-77; GMC K25 Suburban 78-77; GMC K2500 00-88; GMC K2500 86-79; GMC K2500 Suburban 86-79; GMC K2500 Suburban 99-92; GMC K3500 00-80; GMC P2500 89-80; GMC R1500 87; GMC R1500 Suburban 91-87; GMC R2500 87; GMC R2500 Suburban 91-87; GMC R3500 91-87; GMC S15 90-82; GMC S15 Jimmy 91-83; GMC Safari 05-85; GMC Savana 1500 14-03; GMC Savana 2500 05-03; GMC Sierra 1500 19-99; GMC Sierra 1500 Classic 07; GMC Sierra 1500 HD 03-01; GMC Sierra 1500 HD 06-05; GMC Sierra 1500 HD Classic 07; GMC Sierra 1500 Limited 19; GMC Sierra 2500 04-99; GMC Sierra 2500 HD 20-01; GMC Sierra 2500 HD Classic 07; GMC Sierra 3500 06-01; GMC Sierra 3500 Classic 07; GMC Sierra 3500 HD 20-07; GMC Sierra C3 01; GMC Sonoma 04-91; GMC Sprint 77-71; GMC Syclone 91; GMC Typhoon 93-92; GMC V1500 87; GMC V1500 Suburban 91-87; GMC V2500 87; GMC V2500 Suburban 91-87; GMC V3500 91-87; GMC Yukon 20-92; GMC Yukon XL 1500 14-00; GMC Yukon XL 20-15; GMC Yukon XL 2500 13-00; Hummer H2 09-03; Isuzu Ascender 08-03; Isuzu Hombre 00-96; Jeep TJ 06-03; Jeep Wrangler 06-03; Lincoln Continental 79-77; Lincoln Mark IV 76-73; Mercury Cougar 79; Oldsmobile 442 69-64; Oldsmobile 442 71; Oldsmobile 88 57; Oldsmobile 98 84-57; Oldsmobile Bravada 04-96; Oldsmobile Bravada 94-91; Oldsmobile Custom Cruiser 92-71; Oldsmobile Cutlass 81-61; Oldsmobile Cutlass 87-85; Oldsmobile Cutlass 98; Oldsmobile Cutlass Calais 84-78; Oldsmobile Cutlass Cruiser 83-80; Oldsmobile Cutlass Salon 80-75; Oldsmobile Cutlass Salon 87-85; Oldsmobile Cutlass Supreme 88-67; Oldsmobile Cutlass Tiara 76; Oldsmobile Delmont 88 68-67; Oldsmobile Delta 88 85-65; Oldsmobile F85 72-64; Oldsmobile Jetstar 88 67-64; Oldsmobile Starfire 66-61; Oldsmobile Starfire 76; Oldsmobile Super 88 64-57; Oldsmobile Vista Cruiser 75-64; Plymouth Trailduster 81-74; Pontiac 6000 90-89; Pontiac Bonneville 87-57; Pontiac Catalina 81-56; Pontiac Executive 70-67; Pontiac Firebird 02-75; Pontiac Firebird 68-67; Pontiac Grand Am 75-73; Pontiac Grand Am 80-78; Pontiac Grand LeMans 83-75; Pontiac Grand Prix 87-63; Pontiac Grand Safari 78-75; Pontiac Grandville 75-71; Pontiac GTO 73-64; Pontiac LeMans 81-63; Pontiac Parisienne 74-59; Pontiac Parisienne 86-76; Pontiac Safari 70-58; Pontiac Safari 76; Pontiac Safari 89-87; Pontiac Tempest 70-63; Pontiac Ventura 77; Saab 9-7x 07-05
2-3049	Ford LTD II 79; Ford Thunderbird 79; Mercury Cougar 79
2-3100	American Motors AMX 80-79; American Motors Concord 81-78; American Motors Eagle 81-80; American Motors Pacer 80-79; American Motors Spirit 81-79; Dodge Dakota 99-87; Jeep Cherokee 97-95; Jeep Grand Cherokee 97-95
2-3102	Cadillac DeVille 56-53; Cadillac Series 60 Fleetwood 56-50; Cadillac Series 6151-50; Cadillac Series 62 56-52
2-4800 2-4800G 2-4800P	AM General Hummer 01-00; Buick Electra 62-61; Buick LeSabre 62-61; Cadillac DeVille 62-57; Cadillac Series 60 Fleetwood 62-57; Cadillac Series 62 58; Cadillac Series 62 62-60; Cadillac Series 75 Fleetwood 62-59; Checker Marathon 71-69; Checker Marathon 81-74; Chevrolet Avalanche 1500 06-02; Chevrolet Blazer 94; Chevrolet C10 77-75; Chevrolet C10 Pickup 69-68; Chevrolet C10 Pickup 74-73; Chevrolet C10 Suburban 69-68; Chevrolet C10 Suburban 78-73; Chevrolet C1500 01-88; Chevrolet C1500 Suburban 99-92; Chevrolet C20 77-76; Chevrolet C20 Suburban 77-76; Chevrolet C30 Pickup 72-70; Chevrolet Colorado 12-04; Chevrolet Corvette 82-68; Chevrolet G10 95-91; Chevrolet G20 80-76; Chevrolet G20 95-91; Chevrolet G30 77-75; Chevrolet K1500 99-88; Chevrolet K1500 Suburban 99-95; Chevrolet K2500 00-88; Chevrolet K2500 Suburban 99-94; Chevrolet K3500 91-88; Chevrolet R15 01-95; Chevrolet S10 96-94; Chevrolet Silverado 1500 07-99; Chevrolet Silverado 1500 Classic 07; Chevrolet Silverado 99-95; Chevrolet Suburban 1500 06-95; Chevrolet Tahoe 99-95; Chevrolet V30 88; Chevrolet V3500 89; Chrysler Imperial 73-65; Chrysler New Yorker 67-65; Chrysler Newport 67-65; Dodge B1500 98; Dodge B2500 98; Dodge Charger 67-66; Dodge Coronet 67-66; Dodge Dakota 10-99; Dodge Durango 03-98; Dodge Monaco 67-66; Dodge Polara 67-66; Dodge Ram 1500 10-94; Dodge Ram 1500 Van 03-99; Dodge Ram 2500 04-94; Dodge Ram 2500 Van 03-99; Dodge Ram 3500 04-94; Dodge Ram 3500 Van 03-99; Ford Aerostar 97-94; Ford Bronco 96-78; Ford Country Sedan 74-66; Ford Country Squire 74-66; Ford Country Squire 91-87; Ford Crown Victoria 03-92; Ford Crown Victoria 05; Ford Custom 500 77-66; Ford Custom 72-66; Ford E-100 Econoline 83-75; Ford E-100 Econoline Club Wagon 83-75; Ford E-150 Econoline 96-75; Ford E-150 Econoline Club Wagon 96-75; Ford E-250 Econoline 96-75; Ford E-250 Econoline Club Wagon 91-75; Ford E-350 Econoline 96-75; Ford E-350 Econoline Club Wagon 96-77; Ford Elite 76-75; Ford Excursion 01-00; Ford Expedition 06-97; Ford Explorer 10-91; Ford Explorer Sport 03-01; Ford Explorer Sport Trac 05-01; Ford F-100 77-73; Ford F-100 83-79; Ford F-150 07-75; Ford F-150 Heritage 04; Ford F-250 99-68; Ford F-250 HD 97; Ford F-350 97-68; Ford Fairlane 70-66; Ford Galaxie 500 74-66; Ford Galaxie 67-66; Ford Gran Torino 76-72; Ford Granada 78-75; Ford Grand Marquis 02-95; Ford Lobo 03-97; Ford LTD 86-66; Ford LTD Crown Victoria 91-87; Ford LTD II 79-77; Ford Mustang 04-87; Ford Mustang 73-67; Ford P-350 76-75; Ford Ranch Wagon 74-66; Ford Ranchero 79-75; Ford Ranger 11-95; Ford Ranger 86; Ford Thunderbird 67; Ford Thunderbird 79-72; Ford Thunderbird 97-87; Ford Torino 76-68; GMC C15 77-75; GMC C15 Suburban 77-75; GMC C15/C1500 Pickup 74-68; GMC C15/C1500 Suburban 74-68; GMC C1500 99-88; GMC C1500 Suburban 99-92; GMC C25 77-76; GMC C25 Suburban 77-76; GMC C35/C3500 Pickup 72-68; GMC Canyon 12-04; GMC G1500 95-91; GMC G25 78-75; GMC G2500 80-79; GMC G2500 95-91; GMC G35 77-75;

Part#	Application
2-4800 2-4800G 2-4800P (Cont.)	GMC K1500 99-88; GMC K1500 Suburban 99-95; GMC K2500 99-88; GMC K2500 Suburban 99-94; GMC K3500 91-80; GMC P2500 79; GMC Sierra 1500 07-99; GMC Sierra 1500 Classic 07; GMC Sierra 1500 HD 01; GMC Sierra C3 01; GMC Sonoma 96-94; GMC Sprint 72-71; GMC V2500 87; GMC V2500 Suburban 88-87; GMC Yukon 97-94; GMC Yukon XL 1500 06-00; Hummer H104-02; Hummer H106; Hummer H2 03; Isuzu i-280 06; Isuzu i-290 08-07; Isuzu i-350 06; Isuzu i-370 08-07; Jeep Cherokee 01-99; Jeep CJ5 83-82; Jeep CJ7 86-82; Jeep Grand Cherokee 04-00; Jeep Liberty 07-02; Jeep Scrambler 85-82; Jeep TJ 06-03; Jeep Wrangler 06-03; Jeep Wrangler 95-87; Lincoln Aviator 05-03; Lincoln Continental 77-63; Lincoln Continental 80; Lincoln Mark III 71-68; Lincoln Mark IV 72; Lincoln Mark IV 76-75; Lincoln Mark LT 07-06; Lincoln Mark V 79-77; Lincoln Mark VI 83-80; Lincoln Mark VIII 98-93; Lincoln Navigator 06-98; Lincoln Town Car 03-81; Lincoln Versailles 79-77; Mazda B2300 10-01; Mazda B2300 96-95; Mazda B2500 01-98; Mazda B3000 08-97; Mazda B4000 10-98; Mazda B4000 94; Mercury Caliente 67-66; Mercury Colony Park 74-64; Mercury Colony Park 91-87; Mercury Comet 70-66; Mercury Cougar 72-67; Mercury Cougar 79-74; Mercury Cougar 97-89; Mercury Cyclone 70-66; Mercury Grand Marquis 06-75; Mercury Marauder 04-03; Mercury Marauder 70-64; Mercury Marquis 86-67; Mercury Monarch 78-75; Mercury Montclair 68-64; Mercury Montego 76-68; Mercury Monterey 74-64; Mercury Mountaineer 10-97; Mitsubishi Raider 09-06; Nissan Frontier 19-05; Nissan Pathfinder 08-05; Nissan Pathfinder 12; Nissan Titan 18; Nissan Titan XD 21-16; Nissan Xterra 15-05; Oldsmobile 442 70-68; Oldsmobile 98 65; Oldsmobile 98 70-68; Oldsmobile Cutlass 70-68; Oldsmobile Delmont 88 68; Oldsmobile Delta 88 65; Oldsmobile Delta 88 70-68; Oldsmobile F85 70; Oldsmobile Jetstar 88 65; Oldsmobile Starfire 65; Oldsmobile Vista Cruiser 70-68; Plymouth Belvedere 67-66; Plymouth Fury 67-66; Plymouth GTX 67; Plymouth Satellite 67-66; Ram 1500 19-11; Ram Dakota 11; Suzuki Equator 12-09; Toyota Sequoia 24-08; Toyota Tacoma 23-05; Toyota Tundra 24-05
2-4801*	Chevrolet C10 76-75; Chevrolet C10 Pickup 69-68; Chevrolet C10 Suburban 69-68; Chevrolet C20 77-76; Chevrolet C20 Suburban 77-76; Chevrolet C30 Pickup 69-68; Chevrolet Corvette 82-75; Chevrolet G20 80-76; Chevrolet G30 77-75; Ford Bronco 79-78; Ford Bronco 87; Ford Country Sedan 74-66; Ford Country Squire 74-66; Ford Country Squire 87; Ford Custom 500 72-70; Ford Custom 500 77-75; Ford Custom 72-66; Ford E-100 Econoline 83-75; Ford E-100 Econoline Club Wagon 83-75; Ford E-150 Econoline 87-75; Ford E-150 Econoline Club Wagon 87-75; Ford E-250 Econoline 87-75; Ford E-250 Econoline Club Wagon 87-75; Ford E-350 Econoline 87-75; Ford E-350 Econoline Club Wagon 87-77; Ford Elite 76-75; Ford F-100 79; Ford F-100 83-82; Ford F-150 87-75; Ford F-250 87-68; Ford F-350 86-68; Ford Fairlane 70-66; Ford Galaxie 67-66; Ford Gran Torino 76-72; Ford Granada 77-75; Ford LTD 86-75; Ford LTD II 79-77; Ford Mustang 67; Ford Mustang 73-70; Ford P-350 76-75; Ford Ranch Wagon 74-66; Ford Ranchero 79-75; Ford Ranger 86; Ford Thunderbird 79-75; Ford Torino 76-68; GMC C15/C1500 Pickup 69-68; GMC C25 77-76; GMC C25 Suburban 77-76; GMC C35/C3500 Pickup 69-68; GMC G25 78-75; GMC G2500 80-79; GMC G35 75; GMC Jimmy 72-70; GMC P2500 79; GMC Sprint 72-71; Lincoln Continental 77-75; Lincoln Continental 80; Lincoln Mark IV 76-75; Lincoln Mark V 79-77; Lincoln Mark VI 83-80; Lincoln Town Car 86-81; Lincoln Versailles 79-77; Mercury Colony Park 74-64; Mercury Comet 69-66; Mercury Cougar 72-67; Mercury Cougar 79-74; Mercury Cyclone 70-66; Mercury Grand Marquis 86-75; Mercury Marquis 86-75; Mercury Monarch 77-75; Mercury Montclair 68-64; Mercury Montego 76-68; Mercury Park Lane 68-64; Oldsmobile 442 70-68; Toyota Tacoma 15-05
2-4805	Ford Crown Victoria 06-03; Ford Grand Marquis 04-03; Lincoln Town Car 07-03; Mercury Grand Marquis 06
2-4900 2-4900G 2-4900P	Buick Electra 62-61; Buick LeSabre 62-61; Ford Bronco 96-79; Ford Country Sedan 74-63; Ford Country Squire 74-63; Ford Country Squire 91-87; Ford Custom 500 77-64; Ford Custom 72-64; Ford E-100 Econoline 83-79; Ford E-100 Econoline Club Wagon 83-79; Ford E-150 Econoline 88-79; Ford E-150 Econoline Club Wagon 88-79; Ford E-250 Econoline 96-79; Ford E-250 Econoline Club Wagon 91-79; Ford E-350 Econoline 96-79; Ford E-350 Econoline Club Wagon 96-79; Ford Elite 76-75; Ford Explorer 99-97; Ford F-100 77-73; Ford F-100 83-79; Ford F-150 02-00; Ford F-150 96-79; Ford F-150 Heritage 04; Ford F-250 98-79; Ford F-250 HD 97; Ford F-350 97-79; Ford Fairlane 70-63; Ford Falcon 64; Ford Galaxie 500 74-62; Ford Galaxie 67-63; Ford Gran Torino 76-72; Ford Granada 78-75; Ford Lobo 97; Ford LTD 78-65; Ford LTD II 79-77; Ford Mustang 73-67; Ford P-350 76-75; Ford Ranch Wagon 74-64; Ford Ranchero 79-64; Ford Ranger 03-00; Ford Ranger 86; Ford Thunderbird 67; Ford Thunderbird 72; Ford Thunderbird 79-77; Ford Torino 76-68; Lincoln Mark IV 72; Lincoln Mark V 79-77; Mazda B2300 03-01; Mazda B2500 01-00; Mazda B3000 07-00; Mercury Caliente 67-66; Mercury Colony Park 74-63; Mercury Comet 70-66; Mercury Cougar 72-67; Mercury Cougar 79-74; Mercury Cyclone 70-66; Mercury Grand Marquis 78-75; Mercury Marauder 70-63; Mercury Marquis 78-67; Mercury Monarch 78-75; Mercury Montclair 68-64; Mercury Montego 76-68; Mercury Monterey 74-63; Oldsmobile 442 70-68; Oldsmobile 98 65; Oldsmobile 98 70-68; Oldsmobile Cutlass 70-68; Oldsmobile Delmont 88 68; Oldsmobile Delta 88 65; Oldsmobile Delta 88 70-68; Oldsmobile F85 70; Oldsmobile Jetstar 88 65; Oldsmobile Starfire 65; Oldsmobile Vista Cruiser 70-68
3-0044	Toyota Carina 73-71; Toyota Celica 82-71; Toyota Corolla 83-71; Toyota Corona 82-67; Toyota Cressida 84-78; Toyota Mark II 76-72; Toyota Van 85-84
3-0056	Dodge M300 74-68; Dodge M350 74; Dodge M375 73-71; DODGE M400 74-73; Dodge W200 Series 67-61; Dodge W300 76-75; Dodge W300 80-78; Dodge W300 Pickup 74-72; Dodge W350 89-81; Dodge Wm300 Power Wagon 66-60
3-0155 3-0155G 3-0155P	Chevrolet C4500 Kodiak 09-03; Chevrolet C5500 Kodiak 09-03; GMC C4500 Topkick 09-03; GMC C5500 Topkick 09-03; Hino 145 07-05; Hino 185 07-05; Ram 2500 20-13; Ram 3500 20-13; Ram 4500 18-11; Ram 5500 18-11
3-0157	Chevrolet C4500 Kodiak 09-05; Chevrolet C5500 Kodiak 09-05; Ford F-250 Super Duty 22-17; Ford F-350 Super Duty 19-11; Ford F-450 Super Duty 19-05; Ford F-550 Super Duty 19-05; GMC C4500 Topkick 09-05; GMC C5500 Topkick 09-05
3-0188 3-0188G 3-0188P	Chevrolet C4500 Kodiak 09-03; Chevrolet C5500 Kodiak 09-03; Chevrolet Express 2500 19-11; Chevrolet Express 3500 21-10; Chevrolet Express 4500 20-09; Chevrolet Silverado 2500 HD 17-01; Chevrolet Silverado 2500 HD 21-18; Chevrolet Silverado 2500 HD Classic 07; Chevrolet Silverado 3500 07-01; Chevrolet Silverado 3500 Classic 07; Chevrolet Silverado 3500 HD 17-07; Chevrolet Silverado 3500 HD 21-18; Chevrolet W3500 Tiltmaster 04-95; Chevrolet W4500 Tiltmaster 04-00; Dodge Ram 3500 10-09; Ford E-550 Super Duty 03; Ford F-250 Super Duty 18; Ford F-250 Super Duty 22-21; Ford F-450 Super Duty 19-99; Ford F-450 Super Duty 22-21; Ford F53 04-97; Ford F53 09-06; Ford F53 19-11; Ford F-550 Super Duty 18-99; Ford F-550 Super Duty 22-21; Ford F59 18-14; GMC C4500 Topkick 09-03; GMC C5500 Topkick 09-03; GMC Savana 2500 21-11; GMC Savana 3500 21-10; GMC Savana 4500 20-09; GMC Sierra 2500 HD 17-01; GMC Sierra 2500 HD 21-18; GMC Sierra 2500 HD Classic 07; GMC Sierra 3500 07-01; GMC Sierra 3500 Classic 07; GMC Sierra 3500 HD 17-07; GMC Sierra 3500 HD 21-18; GMC W4500 Forward 04-00

* Lube Fitting in Bearing Cap

Part#	Application
3-0332	Chevrolet K30 86-77; Chevrolet V30 88-87; Chevrolet V3500 91-89; Dodge Ram 2500 02-94; Dodge Ram 3500 02-94; Dodge W200 80-75; Dodge W250 93-81; Dodge W300 80-75; Dodge W350 93-81; Ford Excursion 05-00; Ford F-250 79-78; Ford F-250 Super Duty 22-99; Ford F-350 79; Ford F-350 97-85; Ford F-350 Super Duty 19-99; Ford F-450 Super Duty 04-99; Ford F-550 Super Duty 04-99; GMC K35 78-77; GMC K3500 86-79; GMC K3500 89-88; GMC V3500 91-87; International 1300C 69-68; International 1300D 70-69
3-0415	Chevrolet Silverado 2500 HD 07-01; Chevrolet Silverado 2500 HD 13-12; Chevrolet Silverado 2500 HD Classic 07; Chevrolet Silverado 3500 06-01; Chevrolet Silverado 3500 Classic 07; Chevrolet Silverado 3500 HD 13-07; Dodge Ram 1500 09-06; Dodge Ram 2500 10-03; Dodge Ram 3500 10-03; GMC Sierra 2500 HD 06-01; GMC Sierra 2500 HD 13-11; GMC Sierra 2500 HD Classic 07; GMC Sierra 3500 06-01; GMC Sierra 3500 Classic 07; GMC Sierra 3500 HD 13-12; Nissan NV2500 21-12; Nissan NV3500 21-12; Ram 1500 12; Ram 2500 19-11
3-0485	Dodge Ram 1500 09-06; Dodge Ram 2500 10-03; Dodge Ram 3500 09-03
3-0486	Chevrolet Silverado 2500 HD 13-07; Chevrolet Silverado 3500 HD 11-07; Dodge Ram 2500 10-02; Dodge Ram 3500 10-03; Dodge Ram 4500 10-08; Dodge Ram 5500 10-08; GMC Sierra 2500 HD 13-07; GMC Sierra 3500 HD 13-07; Ram 2500 12-11; Ram 3500 12-11
3-0488	Ford F-150 07-04; Ford F-150 Heritage 04; Lincoln Mark LT 07-06; Lincoln Navigator 06-05
3-1555	Dodge Ram 3500 10-07; Dodge Ram 4500 10-08; Dodge Ram 5500 10-08; Ram 2500 20-19; Ram 3500 12-11; Ram 3500 20-19; Ram 4500 12; Ram 5500 12
3-1557	Dodge Ram 2500 10; Dodge Ram 3500 10; Dodge Ram 4500 10-08; Dodge Ram 5500 10-08; Ram 2500 20-11; Ram 3500 19-11; Ram 4500 18-13; Ram 5500 18-13
3-3130	Chevrolet Camaro 93-88; Oldsmobile 88 57; Oldsmobile 98 64-57; Oldsmobile Starfire 63-61; Oldsmobile Super 88 64-57; Pontiac Firebird 93-88
3-3152	Cadillac Commercial Chassis 49-46; Cadillac Series 75 Fleetwood 49-46
4-1090	Hino 238 07-05; Hino 258 07-06; Hino 258LP 07-06; Hino 268 07-05; Isuzu FRR 95; Isuzu NRR 94
6-0675 6-0675GXL	Chevrolet B7 02-95; Chevrolet T6500 98-97; Chevrolet T7500 02-97; GMC B7 02-95; GMC C6000 90; GMC C6000 Topkick 96-90; GMC C6500 Topkick 02-97; GMC C7000 90; GMC C7000 Topkick 96-90; GMC C7500 Topkick 02-97; GMC T6500 98-97; GMC T7500 02-97



THE DRIVELINE EXPERTS

**THESE OE PLATFORMS TRUST NEAPCO.
YOU CAN TOO!**

V E N K A W A S A K I I H H H G C S
P X G R A N D W A G O N E E R K K M
O G F O R A M M O P E L X T M Q Q I
L A N F F M E R C E D E S B E N Z N
A T R U S T E D A U D I S P A F H I
R Y T E S T E D J V X V V M K D J E
I P C N H Y S J O H N D E E R E E N
S C Y G R A N D C H E R O K E E E T
V O L K S W A G O N Y L U C I D P O
F O G N I S E R I E S Y K O P L H G
O N I G H O N D A K A R M A J J J G
O T U S A V F Y O K E L W F C A Y B

Find the following words in the puzzle.
Words are hidden → ↓ and ↘ .

AUDI
CNH
FCA
GRAND CHEROKEE
GRAND WAGONEER
HONDA
I20
JEEP

JOHN DEERE
KARMA
KAWASAKI
LUCID
MERCEDES BENZ
MINI
OPEL
POLARIS

RAM
3 SERIES
TESTED
TOGG
TRUSTED
USA
VOLKSWAGON
YOKE



THE DRIVELINE EXPERTS

**THESE OE PLATFORMS TRUST NEAPCO.
YOU CAN TOO!**

I Q Z M S F I E S T A F O C U S A T
N J L O I X X E X P E D I T I O N J
S X W N E C O S P O R T Y U K O N V
I T S D R R A V I A T O R A N F T G
G D L E R J Y Y F F G D B C M V R A
N X D O A N A V I G A T O R E T A L
I S I L V E R A D O T D T V G S N A
A P B M U S T A N G J U Q K A K S X
S H E X P L O R E R H C B G N O I Y
X G M N E C O N O L I N E H E D T B
N X N J C O L O R A D O Q P N A A Y
A M U S T A N G S V T Y T N O N U Q

Find the following words in the puzzle.
Words are hidden → ↓ and ↘ .

AVIATOR
COLORADO
ECONOLINE
ECOSPORT
EXPEDITION
EXPLORER
F-150
FIESTA

FOCUS
GALAXY
INSIGNIA
MEGANE
MONDEO
MUSTANG
MUSTANG SVT
NAVIGATOR

SIERRA
SILVERADO
SKODA
TRANSIT
YUKON

OEMs Trust Neapco for the First Installation.

OEMs around the world trust Neapco's quality, durability and performance for their vehicles as the original equipment installed at the factories.



You can trust us for the next installation.

You can trust Neapco's quality, durability and performance for all your aftermarket installations too.